


# True Scale Fabric Switches 12200 Series

Release Notes

---

*July 2014*



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to: <http://www.intel.com/design/literature.htm>

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others.

Copyright © 2014, Intel Corporation. All rights reserved.



## Contents

---

<b>1.0 Overview of the Release</b>	4
1.1 Introduction	4
1.2 Audience	4
1.3 If You Need Help	4
1.4 New Features and Enhancements	4
1.5 Installation Requirements	4
1.5.1 Changes to Hardware Support	4
1.5.2 Changes to Firmware Components	4
1.5.3 Changes to Industry Standards Compliance	5
1.6 Miscellaneous	5
1.7 Documentation	5
<b>2.0 Bug Fixes</b>	6
2.1 Known Issues	6
<b>Tables</b>	
1 Related Documentation for this Release	5
2 Resolved Issues	6



## 1.0 Overview of the Release

### 1.1 Introduction

These Release Notes provide a brief overview of the changes introduced into the externally-managed True Scale Fabric Switch 12200. References to more detailed information are provided where necessary. The information contained in this document is intended for supplemental use only; it should be used in conjunction with the documentation provided for each component.

These Release Notes list the new features, system issues closed since the previous release, as well as any known issues.

### 1.2 Audience

The information provided in this document is intended for installers, software support engineers, hardware engineers, and service personnel.

### 1.3 If You Need Help

If you need assistance while working with the True Scale Fabric Switch 12200, contact your Intel approved reseller or Intel True Scale Technical Support:

- By E-mail:  
[ibsupport@intel.com](mailto:ibsupport@intel.com)
- On the Support tab at web site:  
<http://www.intel.com/truescale>

For OEM-specific server platforms supported by this release, contact your OEM.

### 1.4 New Features and Enhancements

The following new features and enhancements have been made between releases 7.2.1.1.16 and 7.3.0.0.15:

- None

### 1.5 Installation Requirements

This release has no special or release-specific installation requirements.

#### 1.5.1 Changes to Hardware Support

There are no release-specific changes to the hardware supported for this release.

#### 1.5.2 Changes to Firmware Components

The True Scale Fabric Switch 12200 externally-managed firmware (EMFW) (Intel\_12000\_V1\_firmware.7.3.0.0.15.emfw) is updated to v7.3.0.0.15.

For upgrade instructions using the FastFabric TUI, refer to the *Intel® True Scale Fabric Suite FastFabric User Guide*.

For upgrade instructions using the `iba_manage_switch` command, refer to the *Intel® OFED+ Host Software User Guide*.



**Note:** The `Intel_12000_V1_firmware.7.3.0.0.15.emfw` firmware file should not be used on 12000-series internally-managed switches.

### 1.5.3 Changes to Industry Standards Compliance

There are no changes to the industry standards for this release.

## 1.6 Miscellaneous

- Before upgrading the 12200 externally-managed switch to 7.3.0.0.15, make certain that either the Intel® True Scale Fabric Suite Software (IFS) v6.0.2.0.28 (or greater), or Intel® OFED+ Host Software Release 7.0.1 or greater is installed on your host.
  - For upgrade instructions using the FastFabric TUI, refer to the *Intel® True Scale Fabric Suite FastFabric User Guide*.
  - For upgrade instructions using the `iba_manage_switch` command, refer to the *Intel® OFED+ Host Software User Guide*.
- Intel products will auto-negotiate with devices that utilize IBTA-compliant auto-negotiation.
- When attaching Intel products to a third-party device, the bit error rate is optimized if the third-party device utilizes attenuation-based tuning.
- The maximum time that a 12200 switch will take to reboot is 120 seconds. Reboot times in your environment may be much less.
- For switches shipped with firmware version 6.1.0.0.72 (or earlier), when connecting two 12200 externally-managed switches together, please see the "Creating an 8x Port: Externally-managed 12200" section of the *Intel® True Scale 12000 Hardware Installation Guide* for cabling recommendations.

**Note:** For 12200 switches shipping with firmware version 6.1.0.2.1 (or newer), the default configuration (1x/4x) is recommended unless there is a specific need to use 8x links.

## 1.7 Documentation

Table 1 lists the Release 7.3 related documentation. All related documentation is available on the Intel download site.

Documentation for Intel Partners is available at the vendors web site.

**Table 1. Related Documentation for this Release**

Document Title
<b>Intel® Hardware Documents</b>
<i>Intel® True Scale 12000 Hardware Installation Guide</i>
<i>Intel® True Scale 12000 Users Guide</i>
<i>Intel® True Scale 12000 CLI Reference Guide</i>
<i>Intel® Adapter Hardware Installation Guide</i>
<b>Intel® OFED+ Documents</b>
<i>Intel® True Scale Fabric Software Installation Guide</i>
<i>Intel® OFED+ Host Software User Guide</i>
<i>Intel® OFED+ Host Software Release Notes</i>
<b>Intel® IFS Documents</b>



**Table 1. Related Documentation for this Release (Continued)**

Document Title
<i>Intel® True Scale Fabric Suite FastFabric User Guide</i>
<i>Intel® True Scale Fabric Suite Fabric Manager User Guide</i>
<i>Intel® True Scale Fabric Suite FastFabric Command Line Interface Reference Guide</i>
<i>Intel® True Scale Fabric Suite Software Release Notes</i>
<b>Intel® Fabric Viewer Documents</b>
<i>Intel® True Scale Fabric Suite Fabric Viewer Online Help</i>
<i>Intel® True Scale Fabric Suite Fabric Viewer Release Notes</i>

## 2.0 Bug Fixes

Table 2 lists the fixes that have been made to the True Scale Fabric Switch 12200 family of QDR InfiniBand\* switches:

**Table 2. Resolved Issues**

Release	Product	Description
7.3.0.0.15	S20	Transmit discards are no longer observed on inter switch links (ISLs).
7.3.0.0.15	S20	Nodes no longer experience intermittent communication failure within the fabric.
7.2.1.1.16	S20	Corrected error recovery mechanisms.

## 2.1 Known Issues

None.

§ §