

Intel Ethernet Controller Products

Release 26.2 Release Notes

Intel Corporation



Revision History

| Revision | Date | Comments |
|----------|------------|------------------|
| 1.0 | March 2021 | Initial release. |



1.0 Overview

This document provides an overview of the changes introduced in the latest Intel[®] Ethernet controller/ adapter family of products. References to more detailed information are provided where necessary. The information contained in this document is intended as supplemental information only; it should be used in conjunction with the documentation provided for each component.

These release notes list the features supported in this software release, known issues, and issues that were resolved during release development.

1.1 Supported Intel® Ethernet Controller Devices

Note: Bold Text indicates the main changes for Software Release 26.2.

| Controller Family | Windows* Driver Version | Linux* Driver Version | FreeBSD Driver Version | NVM Version |
|--------------------------------------------------------------------|-------------------------------|-----------------------------|------------------------------|-------------|
| Intel® Ethernet 800 Series | 1.7.29.0 | 1.4.11 | 0.28.6 | 2.4x |
| Intel® Ethernet 700 Series Intel® Ethernet Network Connection X722 | 1.15.51.x | 2.15.x | 1.12.x | 8.2 |
| Intel® Ethernet 500 Series Intel® Ethernet Controller X550 | 4.1.229.x | 5.11.x | 3.3.x | 3.1 |
| Intel® Ethernet 300 Series | 12.18.12.x | 5.5.x | 2.5.x | N/A |
| Intel® Ethernet 200 Series | 12.19.0.x | 5.5.x | 2.5.x | N/A |
| Intel® Ethernet 225 Series3 | 1.01.x | N/A | N/A | N/A |
| Intel® Ethernet Controller 825983 | 2.4.36.x | 5.10.x | 3.3.x | N/A |
| Intel® Ethernet Controller 8257x3 | 9.16.10.x | 5.5.x | 2.5.x | N/A |

For help identifying a specific network device as well as finding supported devices, click here:

https://www.intel.com/content/www/us/en/support/articles/000005584/network-and-i-o/ethernet-products.html

1.2 New Features

1.2.1 Hardware Support

| Release | New Hardware Support |
|---------|----------------------|
| • 26.2 | None. |

1.2.2 Software Features

| Release | New Software Support |
|---------|--------------------------|
| • 26.2 | Support for FreeBSD 12.2 |

638101-001



1.2.3 Removed Features

| Release | Hardware/Feature Support |
|---------|-----------------------------------------------------------|
| • 26.2 | Drivers and software are no longer tested on FreeBSD 12.1 |

1.2.4 Firmware Features

| Release | New Firmware Support |
|---------|----------------------|
| • 26.2 | None. |



2.0 Fixed Issues

2.1 Intel[®] Ethernet 800 Series

2.1.1 Linux Driver

None for this release.

2.1.2 Windows Driver

None for this release.

2.1.3 Linux RDMA Driver

None for this release.

2.1.4 NVM Update Tool

None for this release.

2.1.5 FreeBSD Driver

None for this release.

2.1.6

None for this release.

2.1.7 Manageability

None for this release.

2.2 Intel[®] 700 Series

None for this release.

2.2.1 Linux driver:

- Express Data Path On the newest Kernels system hang might be observed after eBPF program has been loaded.
- Driver reload or unbind and bind driver on an Intel® Ethernet Converged Network Adapter X710 may cause link down on first port after reboot.
- rx_errors counter double-counts some packets when traffic doesn't pass Cyclic Redundancy Check (CRC).
- Link may be lost after changing MAC address on Physical Function (PF) using Intel(R) Ethernet Network Adapter X722.

2.2.2 Windows driver:

• OID_GEN_RCV_ERROR double-counts some packets when traffic doesn't pass Cyclic Redundancy Check (CRC).

638101-001 5



Under heavy stress on Windows Server 2019, customers might see Event 260: "Failed to move RSS queue from VMQ." in the system event viewer using Intel[®] Ethernet Network Adapter X722. This is due to the driver not moving a particular queue in time for it to move to a new CPU. This is a nonfatal message and traffic is still processed as expected.

2.2.3 Intel(R) Ethernet Flash Firmware Utility:

• One of the ports of Intel[®] Ethernet Network Adapter X710-T2L may not be initialized when using Intel[®] Ethernet Flash Firmware Utility.

2.3 Intel[®] Ethernet 500 Series

None for this release.

2.4 Intel[®] Ethernet 300 Series

None for this release.

2.5 Intel[®] Ethernet 200 Series

None for this release.



3.0 Known Issues

3.1 Intel[®] Ethernet 800 Series

None for this release.

3.2 Intel[®] Ethernet 700, 500 and 300 Series

3.2.1 EFI Driver

• In Bios Controller Name in Controller Handle section contains device path instead of Intel NIC Marketing Name. It's related to Intel® Ethernet Controller X710, Intel® Ethernet Controller X550, Intel® Ethernet Controller I350.

3.2.2 PROSet

• It is not possible to modify a VLAN using IntelNetCmdlets. The Set-IntelNetVLAN command does not display an error.

3.3 Ethernet 700 Series

3.3.1 Linux Driver

• When two VF interfaces are in balance-tlb bonding mode, the ICMP traffic might be interrupted for a few sequences.

3.4 Intel® Ethernet 500 Series

3.4.1 Windows Driver

• OID_GEN_RCV_ERROR double counts some packets when traffic doesn't pass Cyclic Redundancy Check (CRC).

3.4.2 Linux Driver

• The rx_errors counter double counts some packets when traffic doesn't pass Cyclic Redundancy Check (CRC).

3.4.3 Intel[®] Ethernet 300 SeriesESXi Driver

 Not all ports of Intel[®] Ethernet Server Adapter I350 log information about unsupported thermal sensor functionality in vmkernel.log

3.5 Intel[®] Ethernet 200 Series

None for this release.

638101-001 7



3.6 Legacy Devices

Some older $Intel^{\circledR}$ Ethernet adapters do not have full software support for the most recent versions of Microsoft Windows*. Many older Intel Ethernet $^{\circledR}$ adapters have base drivers supplied by Microsoft Windows. Lists of supported devices per operating system are available at:

http://www.intel.com/support/go/network/adapter/nicoscomp.htm



4.0 NVM Upgrade/Downgrade 800 Series/700 Series and X550

Refer to the Feature Support Matrix (FSM) links listed in Related Documents for more detail. FSMs list the exact feature support provided by the NVM and software device drivers for a given release.

5.0 Languages Supported

Note: This only applies to Microsoft Windows and Windows Server Operating Systems.

This release supports the languages listed in the table that follows:

| | Languages |
|----------|---------------------|
| English | Spanish |
| French | Simplified Chinese |
| German | Traditional Chinese |
| Italian | Korean |
| Japanese | Portuguese |

6.0 Related Documents

Contact your Intel representative for technical support about Intel® Ethernet Series devices/adapters.

6.1 Feature Support Matrix

These documents contain additional details of features supported, operating system support, cable/modules, etc.

| Device Series | Support Link |
|---------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|
| Intel® Ethernet 800 Series | https://cdrdv2.intel.com/v1/dl/getContent/630155 |
| Intel® Ethernet 700 Series: — X710/XXV710/XL710 — X722 — X710-TM4/AT2 and V710-AT2 | https://cdrdv2.intel.com/v1/dl/getContent/332191 https://cdrdv2.intel.com/v1/dl/getContent/336882 https://cdrdv2.intel.com/v1/dl/getContent/619407 |
| Intel® Ethernet 500 Series | https://cdrdv2.intel.com/v1/dl/getContent/335253 |
| Intel® Ethernet 300 Series | N/A |
| Intel [®] Ethernet 200 Series | N/A |

638101-001



6.2 Specification Updates

These documents provide the latest information on hardware errata as well as device marking information, SKU information, etc.

| Device Series | Support Link |
|-------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|
| Intel [®] Ethernet 800 Series | https://cdrdv2.intel.com/v1/dl/getContent/616943 |
| Intel [®] Ethernet 700 Series: — X710/XXV710/XL710 — X710-TM4/AT2 and V710-AT2 | https://cdrdv2.intel.com/v1/dl/getContent/331430 https://cdrdv2.intel.com/v1/dl/getContent/615119 |
| Intel [®] Ethernet 500 Series — X550 — X540 | https://cdrdv2.intel.com/v1/dl/getContent/333717 https://cdrdv2.intel.com/v1/dl/getContent/515715 |
| Intel® Ethernet 300 Series | https://cdrdv2.intel.com/v1/dl/getContent/333066 |
| Intel [®] Ethernet 200 Series — I210 — I211 | https://cdrdv2.intel.com/v1/dl/getContent/332763 https://cdrdv2.intel.com/v1/dl/getContent/333015 |

6.3 Software Download Package

The release software download package can be found at:

https://www.intel.com/content/www/us/en/support/products/36773/network-and-i-o/ethernet-products.html

6.4 Intel Product Security Center Advisories

Intel product security center advisories can be found at:

https://www.intel.com/content/www/us/en/security-center/default.html



NOTE: This page intentionally left blank.

638101-001



LEGAL

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

This document (and any related software) is Intel copyrighted material, and your use is governed by the express license under which it is provided to you. Unless the license provides otherwise, you may not use, modify, copy, publish, distribute, disclose or transmit this document (and related materials) without Intel's prior written permission. This document (and related materials) is provided as is, with no express or implied warranties, other than those that are expressly stated in the license.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors which may cause deviations from published specifications.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

Other names and brands may be claimed as the property of others.

© 2021 Intel Corporation.