



BIOS Update Release Notes

PRODUCTS: DN2820FYKH (Standard BIOS)

BIOS Version 0039 - FYBYT10H.86A.0039.2014.0815.1150

About This Release:

- Date: August 15, 2014
- TXE Firmware: 1.0.4.1089
- Framework BIOS Reference Code: Based on 1.3.8
- Integrated Graphics
 - Option ROM: Build 1018 PC 14.34
 - GOP Driver: 7.2.1006
- LAN
 - Option ROM: v2.59 PXE 2.1 Build 083
 - UEFI Driver: 2.0.26
- Visual BIOS: 2.2.7
- UEFI revision: 2.3.1

New Fixes/Features:

- Updated Visual BIOS to version 2.2.8.
- Updated message when no bootable device is found.
- Fixed BIOS and boot issues when SO-DIMMs from certain manufacturers are installed.
- Reduced shutdown time when a USB touch screen is attached.

BIOS Version 0038 - FYBYT10H.86A.0038.2014.0717.1455

About This Release:

- Date: July 17, 2014
- TXE Firmware: 1.0.4.1089
- Framework BIOS Reference Code: Based on 1.3.8
- Integrated Graphics
 - Option ROM: Build 1018 PC 14.34
 - GOP Driver: 7.2.1006
- LAN
 - Option ROM: v2.59 PXE 2.1 Build 083
 - UEFI Driver: 2.0.26
- Visual BIOS: 2.2.7
- UEFI revision: 2.3.1

New Fixes/Features:

- Speeded up BIOS update process - if Intel® ME version has not changed, that segment is skipped during update.

BIOS Version 0037 - FYBYT10H.86A.0037.2014.0710.1336

About This Release:

- Date: July 10, 2014
- TXE Firmware: 1.0.4.1089

*Other names and brands may be claimed as the property of others.

- Framework BIOS Reference Code: Based on 1.3.8
- Integrated Graphics
 - Option ROM: Build 1018 PC 14.34
 - GOP Driver: 7.2.1006
- LAN
 - Option ROM: v2.59 PXE 2.1 Build 083
 - UEFI Driver: 2.0.26
- Visual BIOS: 2.2.7
- UEFI revision: 2.3.1

New Fixes/Features:

- Updated AMI build tool (VEB) to the latest version for OA3 and ITK issues.
- Added support for Intel® Ready Mode Technology.
- Updated Visual BIOS module to v2.2.7.
- Fixed issue where Intel wireless adapters lose connectivity.
- Updated GOP to version 7.2.1006.
- Fixed issue where monitor will not display after S3 resume.

BIOS Version 0034 - FYBYT10H.86A.0034.2014.0513.1413

About This Release:

- Date: May 13, 2014
- TXE Firmware: 1.0.4.1089
- Framework BIOS Reference Code: Based on 1.3.6
- Integrated Graphics
 - Option ROM: Build 1007 PC 14.34
 - GOP Driver: 7.1.1005
- LAN
 - Option ROM: v2.59 PXE 2.1 Build 083
 - UEFI Driver: 2.0.26
- Visual BIOS: 2.2.5
- UEFI revision: 2.3.1

New Fixes/Features:

- Fixed issue where fan speed, temperature, and voltage are not reported in BIOS after modifying duty cycles.
- Enhanced the protection of certain UEFI variables as described in Intel Security Advisory INTEL-SA-00038.
- Fixed issue with BIOS password lengths.
- Fixed Intel ME disable issue.
- Updated GOP and VBIOS.
- Fixed issue where SMBIOS values cannot be set with Intel® Integrator Toolkit.
- Fixed issue where .BMP splash logo files do not display.
- Fixed issue where TXE test fails.
- Fixed issue where system will not boot if PXE Boot is the first boot device.
- Fixed issue with Wake on USB from S4/S5.
- Fixed issue where no error beeps or blinks occur when no memory modules are installed.
- Fixed issue where Intel wireless adapters lose connectivity.
- Fixed issue with USB3/2 compatibility.

*Other names and brands may be claimed as the property of others.

About This Release:

- Date: April 14, 2014
- TXE Firmware: 1.0.4.1089
- Framework BIOS Reference Code: Based on 1.3.6
- Integrated Graphics
 - Option ROM: Build 1007 PC 14.34
 - GOP Driver: 7.1.1005
- LAN
 - Option ROM: v2.59 PXE 2.1 Build 083
 - UEFI Driver: 2.0.26
- Visual BIOS: 2.2.5
- UEFI revision: 2.3.1

New Fixes/Features:

- Modified default values associated with OS Selection options.
 - o Windows 8.x - xHCI mode is enabled
 - o Windows 7 - xHCI mode is set to "smart auto"; Legacy Boot is enabled and greyed out; Wake on USB from S4/S5 is disabled and greyed out
- Updated fan speed control.
- Updated Visual BIOS to version 2.2.5.
- Added OS Selection option in Intel® Integrator Toolkit.
- Updated help text for OS Selection and USB Port.
- Added Wake on USB from S4/S5 support.
- Fixed issue where system wakes up if USB hot-plugging in S5 state.
- Fixed fan speed issue when resuming from S3.
- Fixed issue where Intel 530 series SSD is not recognized.
- Fixed issue where BIOS auto-update feature fails behind a network proxy.
- Fixed issue where system cannot Boot to LAN.
- Fixed issue with disabling USB ports.
- Fixed [WHCK] SMBIOS HCT Test issue.
- Updated processor support.
- Changed Cx state item string to [Lowest CPU Idle Power Setting for C6].
- Updated VBIOS and GOP.
- Disabled HDMI Codec Port "C", to pass WHCK-Audio test.
- Fixed issue where HDD size is incorrect in BIOS Setup.

About This Release:

- Date: March 6, 2014
- TXE Firmware: 1.0.4.1089
- Framework BIOS Reference Code: Based on 1.3.4
- Integrated Graphics
 - Option ROM: Build 1007 PC 14.34
 - GOP Driver: 7.1.1005
- LAN
 - Option ROM: v2.59 PXE 2.1 Build 083
 - UEFI Driver: 2.0.26

- Visual BIOS: 2.2.4
- UEFI revision: 2.3.1

New Fixes/Features:

- Improved fan speed control support.
- Added mouse support under [F10] Boot Menu
- Intel® Integrator Toolkit (ITK) fixes:
 - Cannot update Setup items with ITK.
 - Removed duplicate instance of "Unattended BIOS Configuration"
 - Added specific project name
- Fixed USB2 port compatibility issue
- Fixed issue where USB keyboard/mouse fails after USB3 driver is installed under Legacy operating system.
- Fixed issue where USB mouse does not work in the Boot menu.
- Updated Visual BIOS to version 2.2.4, with Visual Boot Manager version 0.60.
- Improved EFI variable protection for Setup variable.
- Fixed compliance test issue with Intel® Smart Connect Technology.
- Fixed issue where system hangs at POST code 02.
- Updated PXE OPROM to v2.59.
- Updated Realtek* UNDI Driver to 2.026.
- Updated TXE firmware to version 1.0.4.1089 HF4.
- Updated processor microcode.
- Added support for the F1 hotkey to display Advanced Help Text.
- Moved the OS Selection option to the top of the Boot Configuration page.
- Updated message when no bootable device is found.
- Fixed issue where system hangs at POST code 69 if Primary and Secondary Temperature input is PCH and Memory.

BIOS Version 0025 - FYBYT10H.86A.0025.2014.0207.1453

About This Release:

- Date: February 7, 2014
- TXE Firmware: 1.0.2.1060
- Framework BIOS Reference Code: Based on 1.3.2
- Integrated Graphics
 - Option ROM: Build 1007 PC 14.34
 - GOP Driver: 7.1.1005
- LAN
 - Option ROM: v2.57 PXE 2.1 Build 083
 - UEFI Driver: 2.0.23
- Visual BIOS: 2.2.2

New Fixes/Features:

- Fixed issue that prevented installing some operating systems, such as SteamOS*.
- Updated VBIOS to version 1007_20140128 to fix loss of HDMI audio.
- Fixed issue where Windows 7* x64 EFI operating system installation fails.
- Removed [USB3.0 (XHCI mode) support] option from BIOS Setup and enabled it by default.
- Fixed issue where USB legacy SMI support is not available.

*Other names and brands may be claimed as the property of others.

- Fixed issue where Hard Disk Drive Password length did not match the specification.
- Fixed issue where USB 3.0 ports do not work.
- Fixed issue where items are greyed out in the Boot menu.
- Fixed issue where system auto-wakes.
- Added Event Log for CPU Thermal Trip.
- Fixed issue where Graphics item does not show up in Intel® Integrator Toolkit.
- Changed maximum number of USB mass devices from 6 to 16.

BIOS Version 0021 - FYBYT10H.86A.0021.2014.0116.1801

About This Release:

- Date: January 16, 2014
- TXE Firmware: 1.0.2.1060
- Integrated Graphics
 - Option ROM: Build 1007 PC 14.34
 - GOP Driver: 7.1.1005
- LAN
 - Option ROM: v2.57 PXE 2.1 Build 083
 - UEFI Driver: 2.0.23
- Visual BIOS: 2.2.2

New Fixes/Features:

- Fixed issue with LAN Boot order list.
- Fixed issue with S5 wake from USB keyboard/mouse.
- Fixed issue where items disappear from Boot menu.
- Fixed issue where USB cannot wake system from S5.
- Fixed issue where "UEFI: USB: USB Entry for Windows To Go" is sometimes shown in Legacy Boot Priority.
- Fixed issue where Event logo shows "Flash update failed (1)".
- Updated GOP to version 7.1.1005.
- Updated VBIOS to version 1007_20141009.
- Added support for Linux* OS installation.
- Removed USB2.0 support setup item.
- Changed [xHCI mode] to [USB3.0 (xHCI mode) support].
- Created [OS selection] setup item, and default as "Windows 8.X".
- Fixed issue with USB Legacy function.
- Fixed issue with Hard Disk Drive Password valid characters length.
- Fixed Express BIOS Flash update issue.
- Fixed issues with Unknown Devices in Windows 7*.
- Fixed issue with Linux installation.
- Fixed issue where system hangs at POST code 67.
- Fixed issue with VGA Cable output.
- Fixed issue where "Keyboard ready beep" option does not work.
- Added support for Intel® Integrator Toolkit.
- Fixed issue where BIOS update cannot change setup default.
- Fixed issue where Unlimited Boot to Network Attempts option does not work.
- Fixed issue where disabling VT fails.
- Fixed issue where system does not boot if EFI boot is disabled.
- Fixed issue where 19V adaptor warning message is triggered.
- Fixed issue with Legacy USB Key (DOS) detection.

*Other names and brands may be claimed as the property of others.

- Enabled UEFI and Legacy Boot so both can be enabled.
- Added support for more DMI information on System/Board Information page.
- Fixed issue where DMI tool cannot be used in DOS.
- Fixed issue with LAN Boot order list.
- Fixed issue where Boot Menu shows unnecessary UEFI LAN Boot item.
- Fixed issue where monitor is blank if both UEFI and Legacy Boot are enabled.
- Fixed issue with USB Legacy function.
- Fixed issue where Bootable Device Not Detected Function Test fails if both UEFI and Legacy Boot are enabled.
- Fixed issue where USB keyboard does not work.
- Fixed issue with USB device compatibility.
- Fixed issue where system hangs at POST code 32 after S3 resume.
- Fixed issue with Fast Boot.
- Fixed issue with incorrect Hard Disk Drive passwords.
- Fixed issue with BIOS passwords.

Known Errata:

- Some USB keys cannot be detected in BIOS Recovery mode. Format the USB key before Recovery.
- In Windows 7, the system will auto wake up after S5 if a USB key is connected.
- Information about HDMI monitor and HD Audio does not show up in Playback under Sound properties in Control Panel if Legacy Boot is enabled in BIOS. Workaround: disable Legacy Boot in BIOS Setup.

BIOS Version 0015 - FYBYT10H.86A.0015.2013.1210.1722

About This Release:

- Date: December 10, 2013
- TXE Firmware: 1.0.2.1060
- Integrated Graphics
 - Option ROM: Build 1004 PC 14.34
 - GOP Driver: 7.0.1029
- LAN
 - Option ROM: v2.57 PXE 2.1 Build 083
 - UEFI Driver: 2.0.23
- Visual BIOS: 2.2.2

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as

*Other names and brands may be claimed as the property of others.

provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.

Copyright (c) 2014 Intel Corporation.