


# Release Notes

## Intel® Wireless Bluetooth® 21.40.0



<p>Package Version and Supported Operating Systems</p>	<p>21.40.0 for: Microsoft Windows® 10 Windows® 8.1<sup>2</sup> Windows® 7<sup>2</sup></p>
--	---

### Supported Products and Driver Versions

Intel® Wireless Adapter	Windows® 10	Windows® 8.1 <sup>2</sup>	Windows® 7 <sup>2</sup>
Intel® Wi-Fi 6 AX201	21.40.0.1 <sup>1</sup>	N/A	N/A
Intel® Wi-Fi 6 AX200			
Intel® Wireless-AC 9560 <sup>1</sup>			
Intel® Wireless-AC 9462 <sup>1</sup>			
Intel® Wireless-AC 9461 <sup>1</sup>			
Intel® Wireless-AC 9260 <sup>1</sup>			
Intel® Dual Band Wireless-AC 8265	20.100.6.3	20.92.4.2 <sup>1</sup>	20.90.6.3
Intel® Dual Band Wireless-AC 8260			
Intel® Dual Band Wireless-AC 3168		20.92.4.2	
Intel® Dual Band Wireless-AC 3165		20.91.4.2	
Intel® Wireless 7265 Family			

<sup>1</sup>64 Bit only

<sup>2</sup>This release contains updates for Windows® 10 drivers only. Windows 8.1\*and Windows 7\* drivers are the same as the previous release and are included for convenience.

### Key Issues Fixed and Changes on package version 21.40.0

Description of Key Issue	OS
On some systems Bluetooth device can get Yellow Bang sign with Code 54 error in Device Manager after resuming from Sleep mode.	Windows 10®
In rare occasions on some systems Bluetooth device can disappear from Device Manager after Bluetooth driver update.	Windows 10®
Bluetooth connection loss and error message "Network path can not be found" may be observed during the large file transfer.	Windows 10®
General stability improvements and optimizations.	All

Note: Key issues fixed in the OS indicated in the table above.



## **Legal Notices**

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at [intel.com](http://intel.com).

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting [www.intel.com/design/literature.htm](http://www.intel.com/design/literature.htm).

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

© February 2018 Intel Corporation.

