

PRODUCTS: QC71A, QC71B, QC71C, QC71D (Standard BIOS)

BIOS Version 0158 - QCCFL357.0158.2022.1115.1703

About This Release:

- Date: Nov 15, 2022
- ME Firmware: Consumer 12.0.85.1869
- EC Firmware: 1.33.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - Option ROM: 9.2.1019
 - UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - Option ROM: 17.5.0.4055
 - RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - M22906EA 000000EA.pdb
 - M22906ED 000000EA.pdb

New Fixes/Features:

- Fixed issue where Potential hack of BIOS flash EBU DLL.
- Fixed issue where GRUB bootloader vulnerability.
- Fixed issue where Potential improper input validation in Intel NUC BIOS may result in escalation of privilege.

BIOS Version 0156 - QCCFL357.0156.2022.0923.1001

- Date: Sep 23, 2022
- ROM Image Checksum:
 - Filename = QC0156.bin Checksum = 0xB671FD55
 - Filename = QC0156.cap Checksum = 0xBB5E3B04
- ME Firmware: Consumer 12.0.85.1869
- EC Firmware: 1.33.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - Option ROM: 9.2.1019
 - UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - Option ROM: 17.5.0.4055
 - RAID Option ROM: 17.5.0.4055

^{*}Other names and brands may be claimed as the property of others.

- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - M22906EA 000000EA.pdb
 - M22906ED 000000EA.pdb

- 1. Fixed issue where RSB Stuffing Mitigation for Speculative Execution Vulnerability.
- 2. Fixed issue where iFlashV can't update DBIOS, display shows error message "Cannot update BIOS with different platform sku."
- 3. Fixed issue where Patch for Intel NUC 9 vulnerability.
- 4. Fixed issue where S3 Resume Unprotected Pointer vulnerability.

BIOS Version 0150 - QCCFL357.0150.2022.0523.1145

About This Release:

- Date: April 28, 2022
- ROM Image Checksum:
 - Filename = QC0150.bin Checksum = 0xBBCEAE95
 - Filename = QC0150.cap Checksum = 0xC0BAEF1D
- ME Firmware: Consumer 12.0.85.1869
- EC Firmware: 1.33.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - Option ROM: 9.2.1019
 - UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - Option ROM: 17.5.0.4055
 - RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - M22906EA 000000EA.pdb
 - M22906ED 000000EA.pdb

New Fixes/Features:

- Fixed issues with On-board LAN MAC address display error.
- Added ACPI Driver for CCI to fix problem of CCI starting up slowly.
- Added functionality to "F6" key so when pressing it will exit from MFG Mode function in BIOS Setup.
- Fixed OpenSSL security issues.

BIOS Version 0144 - QCCFL357.0144.2022.0124.1433

About This Release:

- Date: Jan 24, 2022
- ROM Image Checksum:
 - Filename = QC0144.bin Checksum = 0xB66D0325
 - Filename = QC0144.cap Checksum = 0xBB594E6A
- ME Firmware: Consumer 12.0.85.1869
- EC Firmware: 1.33.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - Option ROM: 9.2.1019
 - UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - Option ROM: 17.5.0.4055
 - RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - M22906EA 000000EA.pdb
 - M22906ED 000000EA.pdb

New Fixes/Features:

- Fixed: Issue where the system wouldn't enter hibernate when it is set to 180 min.
- **Updated:** EC firmware to 1.33.09.
- Fixed: Issue where the keyboard backlight turned off during boot.
 Updated: ME to 12.0.85.1869 for Windows 11 support.
 Fixed: Issue where keyboard key would not display when pressed.

^{*}Other names and brands may be claimed as the property of others.

About This Release:

- Date: August 12, 2021
- ROM Image Checksum:
 - o Filename = QC0140.bin Checksum = 0xB678A2EF
 - o Filename = QC0140.cap Checksum = 0xBB688E66
- ME Firmware: Consumer 12.0.65.1567
- EC Firmware: 1.31.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - o M22906EA_000000EA.pdb
 - o M22906ED 000000EA.pdb

New Fixes/Features:

 Fixed incorrect memory frequency displayed at 3200MHz when using 2667MHz.

BIOS Version 0138 - QCCFL357.0138.2021.0721.1705

- Date: July 21, 2021
- ROM Image Checksum:
 - o Filename = QC0138.bin Checksum = 0xB6797878
 - o Filename = QC0138.cap Checksum = 0xBB694ACE
- ME Firmware: Consumer 12.0.65.1567
- EC Firmware: 1.31.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - o M22906EA 000000EA.pdb

^{*}Other names and brands may be claimed as the property of others.

- **Updated:** EC FW to v1.31.09 to fix battery capacity and charging issues.
- **Updated:** Changed battery charge voltage level for batteries older than 360 days.
- **Fixed:** The issue that caused some devices not to turn on after updating to BIOS 0126.
- Fixed: When updating the BIOS, if the SATA Mode Selection was set to RAID, the update would cause the SATA Mode Selection to change to AHCI.
- Fixed: Where CCI and the BIOS wouldn't remember the LED settings when the device was rebooted.
- Fixed: The Fn key response time.

QCCFL357.0134.2021.0427.1335 Production BIOS (Lock BIOS)

About This Release:

- Date: Apr 27, 2021
- ROM Image Checksum:
 - o Filename = QC0134.bin Checksum = 0xB69787AD
 - o Filename = QC0134.cap Checksum = 0xBB875B37
- ME Firmware: Consumer 12.0.65.1567
- EC Firmware: 1.29.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - o M22906EA 00000CC.mcb

New Fixes/Features:

- Fixed: Battery charge level reporting and charging issues where the battery wouldn't completely charge (It may take up to three charging cycles for the battery management system to learn to read the charge correctly).
- Updated: EC FW to 1.29.09
- Updated: CPU microcode M22906EA 000000CC.mcb

BIOS Version 0128 - QCCFL357.0128.2021.0312.1538

- Date: Mar 12, 2021
- ROM Image Checksum:
 - o Filename = QC0128.bin Checksum = 0xB69A4F13

^{*}Other names and brands may be claimed as the property of others.

- o Filename = QC0128.cap Checksum = 0xBB8A47C6
- ME Firmware: Consumer 12.0.65.1567
- EC Firmware: 1.26.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

- Updated: EC FW to 1.26.09
- Optimized: Battery charging to improve long-term life

BIOS Version 0122 - QCCFL357.0122.2020.0911.1520

About This Release:

- Date: Sep 11, 2020
- ROM Image Checksum:
 - o Filename = QC0122.bin Checksum = 0xB66A5184
 - o Filename = QC0122.cap Checksum = 0xBB5A3174
- ME Firmware: Consumer 12.0.65.1567
- EC Firmware: 1.25.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

New Fixes/Features:

- Enabled the option, "Display F8 for Activate windows recovery mode" as default.
- Enabled the option, "Intel(R) Speed shift technology" as default.

^{*}Other names and brands may be claimed as the property of others.

About This Release:

- Date: Aug 13, 2020
- ROM Image Checksum: 0xB66C3AA1
- ME Firmware: Consumer 12.0.65.1567
- EC Firmware: 1.25.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Supported Flash Devices:
 - o Winbond W25Q128JV 16MB
- Microcode Updates included in .ROM File:
 - o M22906EA_000000B4.mcb o M22906ED_000000BE.mcb
- Additional Microcode Updates included only in. BIO File:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

New Fixes/Features:

- Enabled: Kernel DMA protection.
- Added: Missing RP3 ACPI table.

BIOS Version 0118 - QCCFL357.0118.2020.0720.1610

About This Release:

- Date: July 20, 2020
- ROM Image Checksum: 0xB66AF702
- ME Firmware: Consumer 12.0.65.1567
- EC Firmware: 1.25.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .ROM File:
 - o M22906EA_000000B4.mcb o M22906ED_000000BE.mcb
- Additional Microcode Updates included only in.BIO File:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

New Fixes/Features:

- Fixed: An issue with the DmiEdit tool.
- Enabled: CPU core voltage lock to enable.

^{*}Other names and brands may be claimed as the property of others.

- Updated: BIOS functionality so that the BIOS can only be updated via the power cord.
- Added: F8 recovery functions.
- Fixed: Issue where GT/GTU prefix showed the incorrect sign.
- Added: Solution for DPC error when running LantencyMon

BIOS Version 0116 - QCCFL357.0116.2020.0619.1354

About This Release:

- Date: June 19, 2020
- ROM Image Checksum: 0xB66FCC58
- ME Firmware: Consumer 12.0.65.1567
- EC Firmware: 1.25.09
- PMC Firmware: 300.2.11.1025
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .ROM File:
 - o M22906EA_000000B4.mcb o M22906ED_000000BE.mcb
- Additional Microcode Updates included only in.BIO File:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

New Fixes/Features:

- Update Me FW: 12.0.65.1567
- Update PMC Firmware: 300.2.11.1025

BIOS Version 0114 - QCCFL357.0114.2020.0401.1544

- Date: April 1, 2020
- ROM Image Checksum: 0xB661C2A7
- ME Firmware: Consumer 12.0.40.1433
- EC Firmware: 1.25.09
- PMC Firmware: 300.2.11.1020
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB

^{*}Other names and brands may be claimed as the property of others.

- Microcode Updates included in .BIN & .CAP Files:
 - o M22906EA_000000B4.mcb
 - o M22906ED_00000BE.mcb

- Added support for: Minimum Fan Duty Cycle.
- Added support for: Battery Life Extension.
- Added support for: Undervoltage.
- Added support for: FN Lock + Esc.
- Added support for: Project Aurora

Known Errata:

• You will NOT be able to flash/recover to previous BIOS versions before 0114.

BIOS Version 0064 - QCCFL357.0064.2020.1226.1657

About This Release:

- Date: March 31, 2020
- ROM Image Checksum: 0xB68445D4
- ME Firmware: Consumer 12.0.40.1433
- EC Firmware: 1.20.09
- PMC Firmware: 300.2.11.1020
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.8.0.4507
 - o RAID Option ROM: 17.8.0.4507
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .ROM File:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb
- Additional Microcode Updates included only in .BIO File:

 - o M22906EA_000000B4.mcb o M22906ED_000000BE.mcb

New Fixes/Features:

- Removed 1.8 seconds of delay to fix a thunderbolt yellow bang
- Added Thunderbolt HRESET Sequence.

BIOS Version 0062 - QCCFL357.0062.2020.1226.1657

- Date: March 13, 2020
- ROM Image Checksum: 0xB68207FB
- ME Firmware: Consumer 12.0.40.1433
- EC Firmware: 1.20.09
- PMC Firmware: 300.2.11.1020
- Boot Guard ACM: 4351

^{*}Other names and brands may be claimed as the property of others.

- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.8.0.4507
 - o RAID Option ROM: 17.8.0.4507
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .ROM File:
 - o M22906EA_000000B4.mcb o M22906ED_000000BE.mcb
- Additional Microcode Updates included only in .BIO File:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

- Added a 1.8 second delay to fix thunderbolt yellow bang.
- Updated BIOS RAID driver/RAID ROM to 17.8.0.4507.
- Fixed Hybrid sleep issues where the system couldn't enter S4
- Enabled FAST BOOT TSE HOTKEY SUPPORT.
- Removed Thunderbolt HRESET Sequence.

BIOS Version 0060 - QCCFL357.0060.2019.1226.1657

About This Release:

- Date: December 26, 2019
- ROM Image Checksum: 0xB6888787
- ME Firmware: Consumer 12.0.40.1433
- EC Firmware: 1.20.09
- PMC Firmware: 300.2.11.1020
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Visual BIOS: Intel Text Setup
- Supported Flash Devices:
 - o WinBond W25Q128JV 16MB
- Microcode Updates included in .BIN & .CAP Files:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

New Fixes/Features:

• Added Thunderbolt HRESET Sequence.

BIOS Version 0058 - QCCFL357.0058.2019.1209.1324

About This Release:

*Other names and brands may be claimed as the property of others.

- Date: December 9, 2019
- ROM Image Checksum: 0xB6848D14
- ME Firmware: Consumer 12.0.40.1433
- EC Firmware: 1.20.09
- PMC Firmware: 300.2.11.1020
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Supported Flash Devices:
 - WinBond W250128JV 16MB
- Microcode Updates included in .ROM File:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb
- Additional Microcode Updates included only in.BIO File:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

- Per INTEL QC PRD v1.8 releasing, BIOS update Chassis Info Type from "09h" to "0Ah".
- Fixed SSD device information.
- Fixed performance issues when using battery.
- Updated EC to version 1.20.09.

BIOS Version 0056 - QCCFL357.0056.2019.1030.1000

About This Release:

- Date: October 30, 2019
- ROM Image Checksum: 0xB6883C22
- ME Firmware: Consumer 12.0.40.1433
- EC Firmware: 1.19.09
- PMC Firmware: 300.2.11.1020
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Supported Flash Devices:
- o WinBond W25Q128JV 16MB
- Microcode Updates included in .ROM File:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb
- Additional Microcode Updates included only in.BIO File:

 - o M22906EA_000000B4.mcb o M22906ED_000000BE.mcb

New Fixes/Features:

• Fixed the thunderbolt issue by doing the following:

^{*}Other names and brands may be claimed as the property of others.

- o Added a 1 second delay.
- o Disabled HRESET.
- o Did not implement UCM related code.
- Added setup HDD Security.
- Fixed the Q-Key function that would randomly become Fan Boost, so that it is a mode change only.
- Added the setup items in Boot -> Secure Boot:
 - o Restore Factory Keys
 - o Reset to Setup Mode
- Updated EC to version 1.19.09.

BIOS Version 0048 - QCCFL357.0048.2019.0808.1937

About This Release:

- Date: August 8, 2019
- ROM Image Checksum: 0xB6860E2B
- ME Firmware: Consumer 12.0.40.1433
- EC Firmware: 1.16.09
- PMC Firmware: 300.2.11.1020
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:
 - o Option ROM: 17.5.0.4055
 - o RAID Option ROM: 17.5.0.4055
- Microcode Updates included in .BIN & .CAP Files:
 - o M22906EA 000000B4.mcb
 - o M22906ED 000000BE.mcb

New Fixes/Features:

- Updated: EC version to 1.16.09.
- Fixed: Where the system would automatically wake up from sleep even when the lid is closed.
- Updated: EFI BIOS raid driver / Legacy OROM raid driver.
- Added: Support for wake on S3 when the top cover is opened.
- Fixed: No display on restart when using Windows® 10 19H1.

BIOS Version 0042 - QCCFL357.0042.2019.0708.1015

- Date: July 8, 2019
- ROM Image Checksum: 0xB68A5398
- ME Firmware: Consumer 12.0.40.1433
- EC Firmware: 1.13.09
- PMC Firmware: 300.2.11.1020
- Boot Guard ACM: 4351
- Memory Reference Code: Based on 0.7.1.104
- Integrated Graphics:
 - o Option ROM: 9.2.1019
 - o UEFI Driver: 9.0.1085
- Intel RST Pre-OS:

^{*}Other names and brands may be claimed as the property of others.

```
Option ROM: 17.2.0.3790
RAID Option ROM: 17.2.0.3790
Microcode Updates included in .BIN & .CAP Files:
M22906EA_000000B4.mcb
M22906ED_000000BE.mcb
```

• Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries. Copyright (c) 2022 Intel Corporation.

^{*}Other names and brands may be claimed as the property of others.