



BIOS Update Release Notes

PRODUCTS: DQ77KB (Standard BIOS)

BIOS Version 0048 - KBQ7710H.86A.0048.2013.0108.1855

About This Release:

- Date: January 8, 2013
- ME Firmware: 8.1.20.1336
- Integrated Graphics Option ROM: 2137 PC 14.34
- SATA RAID Option ROM: v11.6.0.1702
- LAN Option ROM: v1376 PXE 2.1 Build 090
- MEBx Code: Based on Version 8.0.0.0066

New Fixes/Features:

- Fixed issue with no Audio Beep sound.
- Added IGD Flat Panel item in Intel® Integrator Toolkit.
- Fixed issue where blank screen appears in operating system when set to UEFI and LVDS is disabled.
- Added support for 1066 MHz memory.
- Fixed issue with POST logo resolution when using certain legacy video cards.
- Fixed issue where the Password Prompt is not required when Chassis Intrusion is set to Log Only.
- Fixed issue where system halts with permission message and USB keyboard is not available when doing power button recovery with a customized BIOS.
- Fixed RAID issues:
 - Prompt 'Create Volume Fail' error occurs when entering BIOS setup when Secure Boot is enabled and SATA Mode is set to RAID.
 - The BIOS Setup options for UEFI RAID driver/OPROM do not work correctly: only RAID Volume information shows if volumes were previously created but cannot create, delete, or manage it.
- Fixed issue with Secure Boot with non-compliant legacy video card installed.
- Fixed issue with certain TV tuner card.
- Fixed issue with certain video capture card.
- Updated VBIOS to fix issue where there is no display in DOS.
- Updated Intel® ME 8 firmware to version 8.1.20.1336.
- Updated RAID option ROM to version 11.6.0.1702.

BIOS Version 0046 - KBQ7710H.86A.0046.2012.1122.1629

About This Release:

- Date: November 22, 2012
- ME Firmware: 8.1.2.1318
- Integrated Graphics Option ROM: 2137 PC 14.34
- SATA RAID Option ROM: v11.5.0.1111

*Other names and brands may be claimed as the property of others.

- LAN Option ROM: v1376 PXE 2.1 Build 090
- MEBx Code: Based on Version 8.0.0.0066

New Fixes/Features:

- Fixed issue where User Password will be generated again if pressing F9 to load BIOS default values.
- Fixed issue where the Password Prompt is not required when Chassis Intrusion is set to Log Only, if just the Supervisor Password is installed.
- Fixed issue where BIOS recovery fails if using a BIOS image altered with Intel® Integrator Toolkit.
- Fixed issue with USB 3.0 device.
- Updated processor support.
- Fix issue with legacy video cards when Secure Boot is enabled.
- Changed behavior for boot order - now user can still change boot order in BIOS setup after a custom boot order has been set by ITK.
- Added missing jumper detection function.

BIOS Version 0045 - KBQ7710H.86A.0045.2012.1031.1638

About This Release:

- Date: October 31, 2012
- ME Firmware: 8.1.2.1318
- Integrated Graphics Option ROM: 2137 PC 14.34
- SATA RAID Option ROM: v11.5.0.1111
- LAN Option ROM: v1376 PXE 2.1 Build 090
- MEBx Code: Based on Version 8.0.0.0066
- 3rd Generation EFI driver: 3.0.1018
- 2nd Generation EFI driver: 3.0.1018

New Fixes/Features:

- Added Trusted Platform Module Presence option in Setup.
- Removed "Generate New Platform Key" option in Setup.
- Fixed issue with LAN packet drop.
- Fixed issue with IDE-R.

BIOS Version 0044 - KBQ7710H.86A.0044.2012.1019.1704

About This Release:

- Date: October 19, 2012
- ME Firmware: 8.1.2.1318
- Integrated Graphics Option ROM: 2137 PC 14.34
- SATA RAID Option ROM: v11.5.0.1111
- LAN Option ROM: v1376 PXE 2.1 Build 090
- MEBx Code: Based on Version 8.0.0.0066

New Fixes/Features:

- Updated Intel® ME 8 firmware to version 8.1.2.1318.
- Updated MEBx to version 8.0.0.0066.
- Updated processor support.
- Fixed issue with setup display when using SOL.
- Added support for Windows 8*.
- Updated VBIOS to version 2137 PC 14.34.

*Other names and brands may be claimed as the property of others.

BIOS Version 0043 - KBQ7710H.86A.0043.2012.0830.1126

About This Release:

- Date: August 30, 2012
- ME Firmware: 8.0.13.1502
- Integrated Graphics Option ROM: 2132 PC 14.34
- SATA RAID Option ROM: v11.5.0.1111
- LAN Option ROM: v1376 PXE 2.1 Build 090
- MEBx Code: Based on Version 8.0.0.0063

Note:

When using KB0043.BIO with the Intel® Integrator Toolkit (ITK) version 5.0.0, these errors may occur:

- **Error: Unsupported Logo.**
- **The opened BIOS does not have this support.**

If you need to use ITK version 5.0.0 to customize the BIOS for Intel® Desktop Board DQ77KB, do not update to BIOS version 0053. This problem will be fixed in ITK version 5.0.1 and later.

New Fixes/Features:

- Fixed issue where "Press 2" prompt is displayed when updating BIOS with a custom BIOS from Intel® Integrator Toolkit.
- Fixed issue where the error message "CMOS Checksum error" displays when drive is encrypted.
- Fixed issue with UEFI Linux* installation.
- Added setup item "Memory Reference Multiplier".
- Added setup item "Direct Application Launch Button".

BIOS Version 0042 - KBQ7710H.86A.0042.2012.0726.2015

About This Release:

- Date: July 26, 2012
- ME Firmware: 8.0.13.1502
- Integrated Graphics Option ROM: 2132 PC 14.34
- SATA RAID Option ROM: v11.5.0.1111
- LAN Option ROM: v1376 PXE 2.1 Build 090
- MEBx Code: Based on Version 8.0.0.0063

New Fixes/Features:

- Fixed issue where SMBIOS writes to System Serial Number string is not working after previous writes to Manufacturer string.
- Fixed issue where BIOS cannot perform IDE-R.
- Fixed issue where user cannot set Fan responsiveness value in BIOS.
- Fixed issue with Windows* XP SLP 1.0 Activation.
- Added the visible way to enter MEBx.
- Fixed issue where BIOS SATA mode changes to IDE mode after BIOS recovery.
- Updated Intel® ME firmware to version 8.0.13.1502.

BIOS Version 0040 - KBQ7710H.86A.0040.2012.0608.1605

About This Release:

- Date: June 8, 2012

- ME Firmware: 8.0.10.1464
- Integrated Graphics Option ROM: 2132 PC 14.34
- SATA RAID Option ROM: v11.5.0.1111
- LAN Option ROM: v1376 PXE 2.1 Build 090
- MEBx Code: Based on Version 8.0.0.0063

New Fixes/Features:

- Updated BIOS to allow special characters for passwords.
- Fixed issue where the Hide All option does not work for the Expansion Card Text setting in BIOS.
- Fixed issue where L2 cache is incorrect.
- Fixed issue where Supervisor password is still listed and in locked state with full access level.
- Fixed issue with Hard Disk Pre-Delay.
- Fixed issue where there is no Intel® Graphics Performance Analyzers on the Video page in BIOS.
- Fixed issue where IGD Minimum Memory is not listed in BIOS and IGD DVMT Memory is listed in BIOS
- Updated Intel® ME 8 firmware to version 8.0.10.1464.
- Updated MEBx to version 8.0.0.0063.

BIOS Version 0038 - KBQ7710H.86A.0038.2012.0425.1537

About This Release:

- Date: April 25, 2012
- ME Firmware: 8.0.10.1451
- Integrated Graphics Option ROM: 2132 PC 14.34
- SATA RAID Option ROM: v11.0.0.1204
- LAN Option ROM: v1376 PXE 2.1 Build 090
- MEBx Code: Based on Version 8.0.0.0062

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.

*Other names and brands may be claimed as the property of others.

