



BIOS Update Release Notes

PRODUCTS: DH67BL, DH67CF, DH67CL, DH67GD, DH67VR (Standard BIOS)

BIOS Version 0160 - BLH6710H.86A.0160.2012.1204.1156

About This Release:

- Date: December 4, 2012
- ME Firmware: 7.1.60.1193, 8.0.13.1502
- Integrated Graphics Option ROM: Build 2132 PC 14.34
- SATA RAID Option ROM: v11.6.0.1702
- LAN Option ROM: v1403 PXE 2.1 Build 091

Warning:

BIOS version 0151 includes support for 3rd Generation Intel® Core™ processors. Due to structural changes in this BIOS version, once a board has been converted to this version or later, it will no longer be possible to downgrade the BIOS to version 0132 or earlier. Attempting a BIOS downgrade to a previous version may fail - the board BIOS will remain at its current version.

To fully enable support for these processors, follow the special BIOS update steps at [Updating the BIOS on 6 Series chipset desktop boards.](#)

New Fixes/Features:

- Fixed issue with variable reversion.
- Fixed issue with loading fan default values.

BIOS Version 0159 - BLH6710H.86A.0159.2012.0927.1423

About This Release:

- Date: September 27, 2012
- ME Firmware: 7.1.60.1193, 8.0.13.1502
- Integrated Graphics Option ROM: Build 2132 PC 14.34
- SATA RAID Option ROM: v11.6.0.1702
- LAN Option ROM: v1403 PXE 2.1 Build 091

Warning:

BIOS version 0151 includes support for 3rd Generation Intel® Core™ processors. Due to structural changes in this BIOS version, once a board has been converted to this version or later, it will no longer be possible to downgrade the BIOS to version 0132 or earlier. Attempting a BIOS downgrade to a previous version may fail - the board BIOS will remain at its current version.

To fully enable support for these processors, follow the special BIOS update steps at [Updating the BIOS on 6 Series chipset desktop boards.](#)

New Fixes/Features:

- Updated SATA RAID Option ROM to version 11.6.0.1702.
- Updated LAN Option ROM to version 1403.
- Updated processor support.
- Fixed issue with Intel Raid Card RS2WC040.
- Updated Intel® ME 7 firmware to version 7.1.60.1193.
- Fixed warning message displayed when IVB and ME7 are present on same system.
- Fixed issue when EVENT LOGGING = DISABLED, events should not be logged in BIOS, but POST errors should display
- Fixed issue where memory POST error halts POST waiting for a keyboard entry.

BIOS Version 0156 - BLH6710H.86A.0156.2012.0615.1908

About This Release:

- Date: June 15, 2012
- ME Firmware: 7.1.52.1176, 8.0.13.1502
- Integrated Graphics Option ROM: Build 2132 PC 14.34
- SATA RAID Option ROM: v11.2.0.1527
- LAN Option ROM: v1395 PXE 2.1 Build 091

Warning:

BIOS version 0151 includes support for 3rd Generation Intel® Core™ processors. Due to structural changes in this BIOS version, once a board has been converted to this version or later, it will no longer be possible to downgrade the BIOS to version 0132 or earlier. Attempting a BIOS downgrade to a previous version may fail - the board BIOS will remain at its current version.

To fully enable support for these processors, follow the special BIOS update steps at [Updating the BIOS on 6 Series chipset desktop boards.](#)

New Fixes/Features:

- Fixed issue where system configured for RAID mode does not boot to the operating system with UEFI Boot without a keyboard attached.
- Fixed IGD primary/secondary video port issue.
- Fixed Graphics Max Multiplier issue.
- Updated processor support.
- Fixed issue where POST halts waiting for a keyboard entry when event logging is disabled.
- Updated SATA RAID Option ROM to version 11.2.0.1527.
- Updated Intel® ME firmware to versions 7.1.52.1176 and 8.0.13.1502.

BIOS Version 0155 - BLH6710H.86A.0155.2012.0509.1620

About This Release:

- Date: May 9, 2012
- ME Firmware: 7.1.40.1161, 8.0.10.1464

- Integrated Graphics Option ROM: Build 2132 PC 14.34
- SATA RAID Option ROM: v11.1.0.1413
- LAN Option ROM: v1395 PXE 2.1 Build 091

Warning:

BIOS version 0151 includes support for 3rd Generation Intel® Core™ processors. Due to structural changes in this BIOS version, once a board has been converted to this version or later, it will no longer be possible to downgrade the BIOS to version 0132 or earlier. Attempting a BIOS downgrade to a previous version may fail - the board BIOS will remain at its current version.

To fully enable support for these processors, follow the special BIOS update steps at [Updating the BIOS on 6 Series chipset desktop boards.](#)

New Fixes/Features:

- Updated Intel® ME 8 firmware version to 8.0.10.1464.
- Updated Intel® ME 7 firmware version to 7.1.40.1161.
- Updated processor support.
- Updated LAN Option ROM to version 1.3.95 PXE 2.1 Build 091.
- Fixed issue where overclocking does not work as expected after BIOS update.
- Updated VBIOS to version 2132.
- Updated SATA RAID Option ROM to version 11.1.0.1413.
- Fixed issue where system does not boot when third-party RAID card is installed.
- Fixed issue with EDID from analog display using a DVI connector.

BIOS Version 0151 - BLH6710H.86A.0151.2012.0312.1138

About This Release:

- Date: March 12, 2012
- ME Firmware: 7.1.30.1142, 8.0.0.1294
- Integrated Graphics Option ROM: Build 2119 PC 14.34
- SATA RAID Option ROM: v11.0.0.1339
- LAN Option ROM: v1381 PXE 2.1 Build 091

Warning:

BIOS version 0151 includes support for 3rd Generation Intel® Core™ processors. Due to structural changes in this BIOS version, once a board has been converted to this version or later, it will no longer be possible to downgrade the BIOS to version 0132 or earlier. Attempting a BIOS downgrade to a previous version may fail - the board BIOS will remain at its current version.

To fully enable support for these processors, follow the special BIOS update steps at [Updating the BIOS on 6 Series chipset desktop boards.](#)

New Fixes/Features:

- Fixed issue where onboard LAN fails when third party graphics card is installed.

*Other names and brands may be claimed as the property of others.

- Fixed issue where error appears in Device Manager* on the "Audio Device on High Definition Audio Bus".
- Fixed issue where DIMM module compatibility causes an operating system installation problem. Updated LAN Option ROM to version 1381.
- Fixed system boot failure when Memory Configuration is set to Manual - User Defined.
- Added DDR3 low voltage DIMM module support.
- Disabled Keyboard not found event logging.
- Fixed issue where system hangs at POST code '0d' when applying PCIe GEN3 VGA card.
- Updated processor support.
- Updated SATA Option ROM to version 11.0.0.1339.
- Fixed issue where changing default usage for System Fan causes readings to stop appearing.
- Fixed issue where the monitor will not remain in sleep state after waking from S3.
- Fixed HWM IO resource ACPI reporting.
- Fixed issue where system hangs during POST with USB optical drive.

BIOS Version 0132 - BLH6710H.86A.0132.2011.1007.1505

About This Release:

- Date: Oct 07, 2011
- ME Firmware: 7.1.20.1119
- Integrated Graphics Option ROM: Build 2119 PC 14.34
- SATA RAID Option ROM: v10.6.0.1091
- LAN Option ROM: v1365 PXE 2.1 Build 089

New Fixes/Features:

- Updated ITE module support.
- Fixed issue with monitor sleep states.
- Updated processor support.
- Updated Intel® ME firmware to version 7.1.20.1119.
- Added support for Microsoft* OEM Activation 3.0.
- Fixed issue where certain RAID card hangs when pressing Ctrl-G.
- Updated vBIOS to version 2119.
- Added ITE889X module for performance improvement.

BIOS Version 0125 - BLH6710H.86A.0125.2011.0705.1517

About This Release:

- July 5, 2011
- ME Firmware: 7.1.13.1088
- Integrated Graphics Option ROM: Build 2111 PC 14.34
- SATA RAID Option ROM: v10.6.0.1091
- LAN Option ROM: v1365 PXE 2.1 Build 089

New Fixes/Features:

- Updated processor support.
- Updated RAID option ROM to v10.6.0.1091.
- Fixed issue where SATA Port 3 does not support Hot Plug.

*Other names and brands may be claimed as the property of others.

- Fixed issue where re-plugging a USB keyboard can reboot the system.
- Fixed incorrect LAN name in SMBIOS Type 41
- Removed some garbage characters listed in help message of "USB Optimization".
- Removed extra PCI Latency Timer option listed in BIOS.

BIOS Version 0122 - BLH6710H.86A.0122.2011.0601.1554

About This Release:

- June 1, 2011
- ME Firmware: 7.1.13.1088
- Integrated Graphics Option ROM: Build 2111 PC 14.34
- SATA RAID Option ROM: v10.0.0.1046
- LAN Option ROM: v1365 PXE 2.1 Build 089

New Fixes/Features:

- Fixed issue with FSC update load default callback.
- Fixed issue where fan configuration settings are locked instead of hidden in Intel® Integrator Toolkit.

BLH6710H.86A.0119.2011.0523.1030 Production BIOS

About This Release:

- May 23, 2011
- ME Firmware: 7.1.13.1088
- Integrated Graphics Option ROM: Build 2111 PC 14.34
- SATA RAID Option ROM: v10.0.0.1046
- LAN Option ROM: v1365 PXE 2.1 Build 089

Note:

After updating to BIOS version 0119 or newer, you must use the Recovery update method to revert to version 0110 or earlier.

New Fixes/Features:

- Fixed issue where PCIe x1 card is not detected when inserted in a PCIe x16 slot.
- Updated Intel® ME firmware to version 7.1.13.1088.
- Added SATA hot plug functionality.
- Updated processor support.
- Fixed TV tuner card issue.

BIOS Version 0110 - BLH6710H.86A.0110.2011.0415.1506

About This Release:

- April 15, 2011
- ME Firmware: 7.1.11.1069
- Integrated Graphics Option ROM: Build 2111 PC 14.34
- SATA RAID Option ROM: v10.0.0.1046
- LAN Option ROM: v1365 PXE 2.1 Build 089

New Fixes/Features:

- Changed HyperBoot string to Fast Boot.
- Updated RAID info display.
- Updated thermal trip beep pattern.

*Other names and brands may be claimed as the property of others.

- Fixed issue with detected video device priority.
- Fixed issue with Boot to USB functionality.
- Updated VBIOS version.
- Updated ME firmware version.
- Added Lucid Server support.
- Updated fan control for DH67CF.
- Updated SMBios and patch for Intel® Desktop Utilities.
- Added page-up page-down key for setup list-box items.
- Added "No detect" option for each USB port.

BIOS Version 0105 - BLH6710H.86A.0105.2011.0301.1654

About This Release:

- March 01, 2011
- ME Firmware: 7.0.4.1197
- Integrated Graphics Option ROM: Build 2108 PC 14.34
- SATA RAID Option ROM: v10.0.0.1046
- LAN Option ROM: v1365 PXE 2.1 Build 089

New Fixes/Features:

- Disabled HDMI Audio automatic when IGD is not enabled.
- Fixed issue with S3 check for power button recovery.
- Fixed SATA port disable issue.
- Updated processor support.

BLH6710H.86A.0102.2011.0211.2236 Production BIOS

About This Release:

- February 11, 2011
- ME Firmware: 7.0.4.1197
- Integrated Graphics Option ROM: Build 2089 PC 14.34
- SATA RAID Option ROM: v10.0.0.1046
- LAN Option ROM: v1365 PXE 2.1 Build 089

New Fixes/Features:

- Disabled USB ports at early POST.
- Fixed issue with HyperBoot.
- Updated Intel® ME firmware to version 7.0.4.1197.

BIOS Version 0098 - BLH6710H.86A.0098.2011.0114.1739

About This Release:

- January 7, 2011
- ME Firmware: 7.0.2.1164
- Integrated Graphics Option ROM: Build 2089 PC 14.34
- SATA RAID Option ROM: v10.0.0.1046
- LAN Option ROM: v1365 PXE 2.1 Build 089

New Fixes/Features:

- Fixed issue with SMBIOS Max Memory Size on DH67CF.
- Updated Max Non-Turbo ratio now limited by CPU.
- Updated processor support.
- Updated PCI wakeup.

*Other names and brands may be claimed as the property of others.

- Fixed issue with S3 LED behavior.
- Revise SIO behavior to support memory OV DAC only for Manual Memory Voltage issue.
- Modified memory timing for new MRC code.
- Updated fan speed control.
- Removed Fan type item in Setup.
- Removed Current Duty Cycle item in Setup.
- Updated setup item CPU Control Temp, CPU All On Temp and CPU Over Temp with Tcontrol value if FSC variable does not exist.
- Fixed issue where Setup shows slot map even when no PCI/PCIe card installed.
- Fixed iFlash2 update error.
- Removed Burst Mode limitation when using XE processor.
- Changed default hard drive order in AHCI mode.
- Fixed display of processor socket in SMBIOS.
- Updated vBIOS to version 2089.
- Updated setup item Hard Disk Pre-Delay.
- Disabled L0s for USB3.0 loss device issue.
- Fixed issue where IGD Display priority/Detected Video Device Priority has no function.
- Set the default value of the Display F7 to Update Bios option to enabled.
- Updated setup to hide Front Panel Audio option when audio is disabled.
- Fixed issue where a USB device connected to a USB 3.0 port can't be detected under DOS.
- Added warning message about the use of 95W processors for DH67CF.
- Updated Wake on LAN default value.

BIOS Version 0076 - BLH6710H.86A.0076.2010.1115.1959

About This Release:

- November 15, 2010
- ME Firmware: 7.0.1.1141
- Integrated Graphics Option ROM: Build 2080 PC 14.34
- SATA RAID Option ROM: v10.0.0.1046
- LAN Option ROM: v1365 PXE 2.1 Build 089

New Fixes/Features:

- Fixed issue where consumer infrared (CIR) would always show yellow bang even when disabled.
- Fixed issues with burst mode power limit.
- Fixed GFX voltage default.
- Fixed Graphic max multiplier default value.
- Fixed issue with CPU burst mode/sustained mode power limit.
- Fixed eSATA port issue.
- Added setup item for GFX Current Power Limit.
- Updated graphic multiplier defaults.
- Improved consumer infrared function.
- Set graphic voltage override default to 1.2v.
- Updated SMBIOS PCI slot info.
- Updated setup menu exit prompt.
- Fixed issue where Display Port has no audio.

*Other names and brands may be claimed as the property of others.

- Fixed issue where there is an extra reboot with a PCI Express VGA card.
- Updated to ME v1141 firmware.
- Fixed issue with Wake-on-LAN after G3.
- Fixed issue with greyed out Wake-on-LAN from S4/S5 or Deep S4/S5.
- Fixed issue with disabled USB 3.0 controller.
- Updated VBIOS version.
- Modified DIMM slots names
- Updated USB Port mappings.
- Updated PCI slot information in setup.
- Updated UQI tokens.
- Fixed issue where system stops at POST code EB with USB 3.0 device inserted.
- Updated detected video device priority.
- Updated PXE ROM and GbE ROM versions.

BIOS Version 0062 - BLH6710H.86A.0062.2010.1025.1539

About This Release:

- October 25, 2010
- ME Firmware: 7.0.0.1135
- Integrated Graphics Option ROM: Build 2080 PC 14.34
- SATA RAID Option ROM: v10.0.0.1046
- LAN Option ROM: v1363 PXE 2.1 Build 089

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2012 Intel Corporation.

*Other names and brands may be claimed as the property of others.