



## BIOS Update Release Notes

---

### PRODUCTS: NUC7I7DNKE, NUC7I7DNHE, NUC7I7DNBE

---

**BIOS Version 0070 - DNKBLi7v.86A.0070.2020.0924.1014**

#### About This Release:

- Date: September 24, 2020
- ROM Image Checksum: 0x88B0, 0xE6E7 (No FVME)
- ME Firmware: 11.8.80.3746
- EC Firmware: 0D.12.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- SATA non-RAID Option ROM: NA
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25
  
- Supported Flash Devices:

WinBond	W25Q128JVSIQ	16MB
MACRONIX	MX25L12850F	16MB
GigaDevice	GD25B127D	16MB
- Microcode Updates included in .ROM File:  
MC0806EA\_000000D6.mcb
- Additional Microcode Updates included only in .BIO File:  
MC0806EA\_000000D6.mcb

#### New Fixes/Features:

- Updated ME firmware to version 11.8.80.3746.
- Updated microcode to MC0806E9\_000000D6.
- Updated BIOS code for security fixes.

#### Known Errata:

- Due to the Intel® ME firmware update in BIOS version 0070, you can't downgrade to version 0069 or earlier.

**BIOS Version 0069 - DNKBLi7v.86A.0069.2020.0610.1805**

#### About This Release:

- Date: June 10, 2020
- ROM Image Checksum: 0x16EC, 0xA473 (No FVME)
- ME Firmware: 11.8.77.3664
- EC Firmware: 0D.12.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010

- Integrated Graphics:
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1095
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25
- Supported Flash Devices:
 

WinBond	W25Q128JVSIQ	16MB
MACRONIX	MX25L12850F	16MB
GigaDevice	GD25B127D	16MB
- Microcode Updates included in .ROM & .BIO Files:
  - MC0806EA\_000000B4.mcb

#### **New Fixes/Features:**

- Updated ME Firmware to 11.8.77.3664.
- Fixed issue where custom BIOS from ITK fails to install when unattended BIOS configuration is set to never prompt.
- Updated BIOS code for security fixes.

#### **Known Errata:**

- Due to the Intel® ME firmware update in BIOS version 0069, you can't downgrade to version 0068 or earlier.

<b>BIOS Version 0068 - DNKBLi7v.86A.0068.2020.0312.1938</b>
---

#### **About This Release:**

- Date: March 12, 2020
- ROM Image Checksum: 0xD4CB, 0x6252 (No FVME)
- ME Firmware: 11.8.70.3626
- EC Firmware: 0D.12.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010
- Integrated Graphics:
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25
- Supported Flash Devices:
 

WinBond	W25Q128JVSIQ	16MB
MACRONIX	MX25L12850F	16MB
GigaDevice	GD25B127D	16MB
- Microcode Updates included in .ROM & .BIO Files:
  - MC0806EA\_000000B4.mcb

#### **New Fixes/Features:**

- Updated BIOS code for security fixes.
- Fixed issues regarding system reboot and system wake up.
- Fixed issue to "Set default Family Name" to "DN".

- Updated ME Firmware version to 11.8.70.3626.

**BIOS Version 0067 - DNKBLi7v.86A.0067.2019.1101.1743****About This Release:**

- Date: November 01, 2019
- ROM Image Checksum: 0x6E19, 0xFC69 (No FVME)
- ME Firmware: 11.8.65.3590
- EC Firmware: 0D.12.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010
- Integrated Graphics:
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25
  
- Supported Flash Devices:

WinBond	W25Q128JVSIQ	16MB
MACRONIX	MX25L12850F	16MB
GigaDevice	GD25B127D	16MB
  
- Microcode Updates included in .ROM & .BIO Files:  
MC0806EA\_000000B4.mcb

**New Fixes/Features:**

- Fixed issue where "Hybrid BIOS USB recovery".
- Fixed issue where "Chassis value type changed during flash by BIO" for Microsoft request.
- Fixed issue where "SMBIOS Field update BIOS" for Microsoft request.
- Implemented security fixes
- Added support for "EFI ERASE BLOCK Protocol support for Android".
- Updated EC to version 12.00.

**BIOS Version 0066 - DNKBLi7v.86A.0066.2019.0710.1150****About This Release:**

- Date: July 10, 2019
- ROM Image Checksum: 0x3CD6, 0xCB26 (No FVME)
- ME Firmware: 11.8.65.3590
- EC Firmware: 0D.11.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25
- Supported Flash Devices:

WinBond	W25Q128JVSIQ	16MB
MACRONIX	MX25L12850F	16MB

GigaDevice GD25B127D 16MB

- Microcode Updates included in .ROM File:  
MC0806EA\_000000B4.mcb
- Additional Microcode Updates included only in .BIO File:  
MC0806EA\_000000B4.mcb

**New Fixes/Features:**

- Fixed issue where there's no display when using eDP panel.
- Fixed issue where BIOS password isn't recognized.
- Modified BIOS code for security fix

**BIOS Version 0065 - DNKBLi7v.86A.0065.2019.0611.1424**

**About This Release:**

- Date: June 11, 2019
- ROM Image Checksum: 0x6746, 0xF596 (No FVME)
- ME Firmware: 11.8.65.3590
- EC Firmware: 0D.11.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25
- Supported Flash Devices:

WinBond	W25Q128JVSIQ	16MB
MACRONIX	MX25L12850F	16MB
GigaDevice	GD25B127D	16MB
- Microcode Updates included in .ROM File:  
MC0806EA\_000000B4.mcb
- Additional Microcode Updates included only in .BIO File:  
MC0806EA\_000000B4.mcb

**New Fixes/Features:**

- Updated CPU microcode to MC0806E9\_000000B4.
- Removed "SW Control" option from "Button LED" item in BIOS Setup.

**BIOS Version 0064 - DNKBLi7v.86A.0064.2019.0524.1002**

**About This Release:**

- Date: May 24, 2019
- ROM Image Checksum: 0x359E, 0xC3EE (No FVME)
- ME Firmware: 11.8.65.3590
- EC Firmware: 0D.11.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- SATA non-RAID Option ROM: NA

- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Fixed TPM provision test failure.

**BIOS Version 0063 - DNKBLi7v.86A.0063.2019.0503.1906**

**About This Release:**

- Date: May 3, 2019
- ROM Image Checksum: 0x36A0, 0xC4F0 (No FVME)
- ME Firmware: 11.8.65.3590
- EC Firmware: 0D.11.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Updated Intel ME firmware to version 11.8.65.3590.
- Modified BIOS code for security fixes.
- Changed enclosure type default to 0x23.

**Known Errata:**

- Due to the Intel® ME firmware update in BIOS version 0063, you can't downgrade to version 0062 or earlier.

**BIOS Version 0062 - DNKBLi7v.86A.0062.2019.0304.1800**

**About This Release:**

- Date: March 4, 2019
- ME Firmware: 11.8.55.3510
- EC Firmware: 0D.11.00
- Memory Reference Code: Based on 3.6.4
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Fixed issue where system doesn't resume from S3 properly.
- Fixed issue where there's no display when using eDP panel.
- Updated BIOS code for security fixes.

**BIOS Version 0060 - DNKBLi7v.86A.0060.2018.1220.1528**

**About This Release:**

- Date: December 20, 2018
- ME Firmware: 11.8.50.3510
- EC Firmware: 0D.11.00
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Fixed issue where Hyperthreading can't be disabled using ITK.
- Fixed issue where disk encryption on Samsung eDrive doesn't work.
- Fixed issue where BIOS update process in Linux hangs on POST code with 48FE.
- Updated EC firmware to version 11.00.

**BIOS Version 0059 - DNKBLi7v.86A.0059.2018.1129.1445**

**About This Release:**

- Date: November 29, 2018
- ME Firmware: 11.8.55.3510
- EC Firmware: 0D.10.00
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Set PCIe ASPM function to Disabled.

**BIOS Version 0058 - DNKBLi7v.86A.0058.2018.1115.1528**

**About This Release:**

- Date: November 15, 2018
- ME Firmware: 11.8.55.3510
- EC Firmware: 0D.10.00
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054

- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Added NVME hard drive string ID.
- Modified BIOS embedded DP setting.

**BIOS Version 0057 - DNKBLi7v.86A.0057.2018.1030.1636**

**About This Release:**

- Date: October 30, 2018
- ME Firmware: 11.8.55.3510
- EC Firmware: 0D.10.00
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Added USB Host/Device mode switch item in USB Configuration page.
- Fixed issue where Persistence Mode can't be set to default using ITK 6.1.8.

**BIOS Version 0056 - DNKBLi7v.86A.0056.2018.1003.1622**

**About This Release:**

- Date: October 3, 2018
- ME Firmware: 11.8.55.3510
- EC Firmware: 0D.10.00
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - o Option ROM: 9.0.1051
  - o UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- BIOS functionality enhancements.

**BIOS Version 0055 - DNKBLi7v.86A.0055.2018.0921.1802**

**About This Release:**

- Date: September 21, 2018
- ME Firmware: 11.8.55.3510
- EC Firmware: 0D.10.00

- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Fixed issue where system won't boot when NVME password is enabled then disabled on Intel E6100P SSD.

**BIOS Version 0053 - DNKBLi7v.86A.0053.2018.0904.1601**

**About This Release:**

- Date: September 4, 2018
- ME Firmware: 11.8.55.3510
- EC Firmware: 0D.10.00
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Fixed issue where the front panel LED blink code fails if memory is missing.
- Fixed issue with USB after updating BIOS from version 0044 to version 0052 via Jumper recovery.
- Updated Intel® ME firmware to version 11.8.55.3510.
- Updated BIOS Gigabit Ethernet binary to fix SSID issue.
- Due to the Intel® ME firmware update in BIOS version 0053, you can't downgrade to version 0052 or earlier.

**BIOS Version 0052 - DNKBLi7v.86A.0052.2018.0808.1344**

**About This Release:**

- Date: August 8, 2018
- ME Firmware: 11.8.50.3425
- EC Firmware: 0D.10.00
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25



**New Fixes/Features:**

- Fixed the issue that would cause the system not to power on.
- Fixed the issue where M.2 PCIe SSDs would run at Generation 2 speeds.†
- Removed Intel Ready Mode.
- Fixed the issue that would cause the system to automatically wake from S3 when a device was connected to the 3.5mm jack.
- Fixed the issue that would cause the wireless and Bluetooth options to disappear after they were enabled.
- Fixed the issue where "Wake on USB from S5" wouldn't work ("USB S4/S5 Power must be turned on to see this option).

† To fix the M.2 issue, the BIOS must be installed using the [jumper recovery method](#).

<b>BIOS Version 0050 - DNKBLi7v.86A.0050.2018.0716.1602</b>
---

**About This Release:**

- Date: July 16, 2018
- ME Firmware: 11.8.50.3425
- EC Firmware: 0D.10.00
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics:
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Added the feature to keep USB power during System Reset.
- Fixed the issue where BIOS recovery wouldn't work.
- Fixed the Wake on LAN from S3 issue where the monitor wouldn't wake up.
- Updated CPU Microcode (Security Advisory-00115).

<b>BIOS Version 0047 - DNKBLi7v.86A.0047.2018.0613.1802</b>
---

**About This Release:**

- Date: June 13, 2018
- ME Firmware: 11.8.50.3425
- EC Firmware: 0D.10.00
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Enabled fanless mode.
- Updated the EC to version 10.00
- Fixed the issue where the splash screen logo would be askew in the OS recovery process.
- Improved the fault tolerance when using the recovery process.
- Updated the TPM 2.0 security.
- Added TPM FW update functionality.

**BIOS Version 0040 - DNKBLi7v.86A.0040.2018.0315.1507**

**About This Release:**

- Date: March 15, 2018
- ME Firmware: 11.8.50.3425
- EC Firmware: 0D.09.00
- MEBx Revision: 11.0.0.0010
- Integrated Graphics:
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Updated EC firmware version to 9.00.
- Fixed USB provisioning setting.
- Fixed issue with disabling USB port in M.2 Wireless Slot for Bluetooth.
- Fixed issue where fan control mode default value changes after F10 and re-entering BIOS.
- Fixed issue with changing Secondary Temperature Sensor Value.

**BIOS Version 0039 - DNKBLi7v.86A.0039.2018.0222.1736**

**About This Release:**

- Date: February 22, 2018
- ME Firmware: 11.8.50.3425
- EC Firmware: 0D.08.00
- MEBx Revision: 11.0.0.0010
- Integrated Graphics:
  - o Option ROM: 9.0.1051
  - o UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Updated CPU Microcode (Security Advisory-00088)

**BIOS Version 0037 - DNKBLi7v.86A.0037.2018.0131.0828**

**About This Release:**

- Date: January 31, 2018

- ME Firmware: 11.8.50.3425
- EC Firmware: 0D.08.00
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
  - Option ROM: 9.0.1051
  - UEFI Driver: 9.0.1066
- SATA RAID Option ROM: 15.7.0.3054
- AHCI Code: Based on AHCI\_14
- LAN Option ROM: PXE 2.1 Build 092
- Visual BIOS: 2.2.25

**New Fixes/Features:**

- Initial production BIOS release

---

**LEGAL INFORMATION**

---

**Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.**

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, lifesaving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.  
Copyright (c) 2018 Intel Corporation.