



# Release Notes

## Intel® Wireless Bluetooth® 22.30.0

Package Version and Supported Operating Systems	22.30.0 for: Microsoft Windows® 10
---	------------------------------------

### Supported Products and Driver Versions

Intel® Wireless Adapter	Windows® 10
Intel® Wi-Fi 6E AX210	22.30.0.4 <sup>1</sup>
Intel® Wi-Fi 6 AX201	
Intel® Wi-Fi 6 AX200	
Intel® Wireless-AC 9560	
Intel® Wireless-AC 9462	
Intel® Wireless-AC 9461	
Intel® Wireless-AC 9260	
Intel® Dual Band Wireless-AC 8265	
Intel® Dual Band Wireless-AC 8260	20.100.7.1
Intel® Dual Band Wireless-AC 3168	
Intel® Dual Band Wireless-AC 3165	
Intel® Wireless 7265 Family	

<sup>1</sup>64 Bit only

### Key Issues Fixed and Changes on package version 22.30.0

Description of Key Issue
On some systems, audio noise may be observed during HFP voice call.
Discontinuity of audio during a Teams call can occur on some devices.
Occasionally, the Bluetooth LE mouse may stop working.
Intel® Wireless Bluetooth® 22.30.0 driver has been updated to include functional and security updates. Users should update to the latest version.

Note: Key issues fixed in the OS indicated in the table above.



## Key Issues Fixed and Changes on package version 22.20.0

Description of Key Issue
On some systems, Bluetooth device may show a yellow bang in Device Manager after resuming from Hibernation mode.
On some systems, a Bluetooth mouse may show disconnection after resuming from Modern Standby mode.
Intel® Wireless Bluetooth® 22.20.0 driver has been updated to include functional and security updates. Users should update to the latest version.

Note: Key issues fixed in the OS indicated in the table above.

### Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting [www.intel.com/design/literature.htm](http://www.intel.com/design/literature.htm).

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.



