



BIOS Update Release Notes

PRODUCTS: NUC7CJYH, NUC7PJYH, NUC7CJYSAL

BIOS Version 0060 - JYGLKCPX.86A.0060.2021.0325.1143

About This Release:

- Date: Mar 25, 2021
- ROM Image Checksum: 0x9241
- TXE Firmware: 4.0.30.1386
- EC Firmware: 2.27
- PMC Firmware: v06.08.00
- Framework Reference Code: Based on 2.2.1.0
- Integrated Graphics:
 - Option ROM: v13.0.1005
 - UEFI Driver: v13.0.1018
- LAN Option ROM: PXE-2.1 BUILD (083) v2.67
- Visual Bios: 2.2.23

- Supported Flash Devices:

WinBond	W25Q128FWSIQ	16MB (1.8V)
MACRONIX	MX25U12873FM2I	16MB (1.8V)
GigaDevice	GD25LB128D	16MB (1.8V)

- Microcode Updates included in .ROM & .BIO Files:
 - M01706A1_00000034.PDB
 - M01706A8_00000018.PDB

New Fixes/Features:

- Fixed booting issues with LINUX OS systems when upgrading BIOS version.

BIOS Version 0059 - JYGLKCPX.86A.0059.2021.0305.2156

About This Release:

- Date: Mar 05, 2021
- ROM Image Checksum: 0x286C
- TXE Firmware: 4.0.30.1386
- EC Firmware: 2.27
- PMC Firmware: v06.08.00
- Framework Reference Code: Based on 2.2.1.0
- Integrated Graphics:
 - Option ROM: v13.0.1005
 - UEFI Driver: v13.0.1018
- LAN Option ROM: PXE-2.1 BUILD (083) v2.67
- Visual Bios: 2.2.23

- Supported Flash Devices:

WinBond	W25Q128FWSIQ	16MB (1.8V)
MACRONIX	MX25U12873FM2I	16MB (1.8V)

*Other names and brands may be claimed as the property of others.

GigaDevice GD25LB128D 16MB(1.8V)

- Microcode Updates included in .ROM & .BIO Files:
M01706A1_00000034.PDB
M01706A8_00000018.PDB

New Fixes/Features:

- Fixed issue with NTFS DXE driver when parsing NTFS file system.
- Fixed LINUX boot issue.
- Updated Audio Codec software.
- Updated Visual BIOS Option ROM to v13.0.1005

BIOS Version 0058 - JYGLKCPX.86A.0058.2020.1210.1603

About This Release:

- Date: December 10, 2020
- ROM Image Checksum: 0xE2AF
- TXE Firmware: 4.0.30.1386
- EC Firmware: 2.27
- PMC Firmware: v06.08.00
- Framework Reference Code: Based on 2.2.1.0
- Integrated Graphics:
 - Option ROM: v13.0.1005
 - UEFI Driver: v13.0.1018
- LAN Option ROM: PXE-2.1 BUILD (083) v2.67
- Visual Bios: 2.2.23
- Supported Flash Devices:

WinBond	W25Q128FWSIQ	16MB(1.8V)
MACRONIX	MX25U12873FM2I	16MB(1.8V)
GigaDevice	GD25LB128D	16MB(1.8V)
- Microcode Updates included in .ROM & .BIO Files:
M01706A1_00000034.PDB
M01706A8_00000018.PDB

New Fixes/Features:

- Updated TXE to 4.0.30.1386
- Updated PMC firmware to v06.08.00
- Updated ME Firmware to v4.0.30.1386
- Updated VBIOS to v13.0.1005.
- Updated option ROM UEFI driver to v13.0.1018.
- Added the Card reader setting for JY refresh.
- Fixed the issue where "[JY Refresh]JY board microcode not loaded".
- Fixed the issue where "[JY Refresh]BIOS Startup Sound Enabled Halt Intel Logo".
- Fixed the issue where "[JY Refresh]SGX device lost in device manager".
- Fixed the issue where "[JY Refresh] Press PWR button can't shutdown/sleep SUT in OS".
- Updated BIOS code for security fixes.

Known Errata:

*Other names and brands may be claimed as the property of others.

- Due to the CPU microcode update in BIOS version 0058, you can't downgrade to version 0057 or earlier.

BIOS Version 0057 - JYGLKCPX.86A.0057.2020.1020.1637

About This Release:

- Date: October 20, 2020
- ROM Image Checksum: 0xA1B5
- TXE Firmware: 4.0.26.1334
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.10178
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

- Supported Flash Devices:

WinBond	W25Q128FWSIQ	16MB (1.8V)
MACRONIX	MX25U12873FM2I	16MB (1.8V)
GigaDevice	GD25LB128D	16MB (1.8V)

- Microcode Updates included in .ROM & .BIO Files:
M01706A1_00000034.PDB

New Fixes/Features:

- Fixed issue where S3 resume Power limit setting fails.
- Fixed issue where profiles can't be saved or updated.

BIOS Version 0056 - JYGLKCPX.86A.0056.2020.0902.1338

About This Release:

- Date: Sep 02, 2020
- ROM Image Checksum: 0x1030
- TXE Firmware: 4.0.26.1334
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.10178
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

- Supported Flash Devices:

WinBond	W25Q128FWSIQ	16MB (1.8V)
MACRONIX	MX25U12873FM2I	16MB (1.8V)
GigaDevice	GD25LB128D	16MB (1.8V)

- Microcode Updates included in .ROM & .BIO Files:
M01706A1_00000032.PDB

New Fixes/Features:

*Other names and brands may be claimed as the property of others.

- Fixed issue where BIOS showed incorrect SATA Speed.
- TXE Firmware Update to 4.0.26.1334.

BIOS Version 0055 - JYGLKCPX.86A.0055.2020.0603.1745

About This Release:

- Date: June 03, 2020
- ROM Image Checksum: 0xA656
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.10178
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23
- Supported Flash Devices:

WinBond	W25Q128FWSIQ	16MB(1.8V)
MACRONIX	MX25U12873FM2I	16MB(1.8V)
GigaDevice	GD25LB128D	16MB(1.8V)
- Microcode Updates included in .ROM & .BIO Files:
 - M01706A1_00000032.PDB

New Fixes/Features:

- Fixed issue regarding no display after changing video settings.
- Fixed issue with abnormal behavior in lock manufacturing mode.

BIOS Version 0054 - JYGLKCPX.86A.0054.2020.0220.1438

About This Release:

- Date: February 20, 2020
- ROM Image Checksum: 0x676F
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.10178
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23
- Supported Flash Devices:

WinBond	W25Q128FWSIQ	16MB(1.8V)
MACRONIX	MX25U12873FM2I	16MB(1.8V)
GigaDevice	GD25LB128D	16MB(1.8V)
- Microcode Updates included in .ROM & .BIO Files:
 - M01706A1_00000032.PDB

New Fixes/Features:

- Updated BIOS code for security fixes.

*Other names and brands may be claimed as the property of others.

- Fixed issue where "Set default Family Name" for Microsoft MDA request.
- Fixed PXE boot message not being displayed in UEFI.

BIOS Version 0053 - JYGLKCPX.86A.0053.2019.1015.1510

About This Release:

- Date: October 15, 2019
- ROM Image Checksum: 0xEB86
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.10178
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23
- Supported Flash Devices:
 - WinBond W25Q128FWSIQ 16MB (1.8V)
 - MACRONIX MX25U12873FM2I 16MB (1.8V)
 - GigaDevice GD25LB128D 16MB (1.8V)
- Microcode Updates included in .ROM & .BIO Files:
 - M01706A1_00000032.PDB

New Fixes/Features:

- Security enhancements.
- Updated BIOS code for BIOS recovery with USB flash drive.

BIOS Version 0052 - JYGLKCPX.86A.0052.2019.0904.1413

About This Release:

- Date: September 04, 2019
- ROM Image Checksum: 0xDC8A
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.10178
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23
- Supported Flash Devices:
 - WinBond W25Q128FWSIQ 16MB (1.8V)
 - MACRONIX MX25U12873FM2I 16MB (1.8V)
 - GigaDevice GD25LB128D 16MB (1.8V)
- Microcode Updates included in .ROM & .BIO Files:
 - M01706A1_0000002E.PDB

New Fixes/Features:

- Security enhancements.
- Improved BIOS code for issues related to Hybrid BIOS USB recovery.

*Other names and brands may be claimed as the property of others.

BIOS Version 0051 - JYGLKCPX.86A.0051.2019.0614.1047

About This Release:

- Date: June 14, 2019
- ROM Image Checksum:0x5D93
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5
- Integrated Graphics
- Option ROM: v13.0.1002
UEFI Driver: v13.0.10178
- LAN
Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23
- Supported Flash Devices:

WinBond	W25Q128FWSIQ	16MB(1.8V)
MACRONIX	MX25U12873FM2I	16MB(1.8V)
GigaDevice	GD25LB128D	16MB(1.8V)
- Microcode Updates included in .ROM File:
M01706A1_0000002E.PDB
- Additional Microcode Updates included only in .BIO File:
M01706A1_0000002E.PDB

New Fixes/Features:

- Updated CPU Microcode to M01706A1_0000002E for security fix.
- Removed "SW Control" option from "Button LED" item in BIOS Setup.

BIOS Version 0050 - JYGLKCPX.86A.0050.2019.0418.1441

About This Release:

- Date: April 18, 2019
- TXE Firmware: 4.0.10.1288
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5
- Integrated Graphics
- Option ROM: v13.0.1002
UEFI Driver: v13.0.10178
- LAN
Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Updated BIOS to display ENERGY STAR logo on Mini PC SKUs.
- Changed enclosure type default to 0x23.

BIOS Version 0049 - JYGLKCPX.86A.0049.2019.0401.1038

About This Release:

- Date: April 1, 2019
- TXE Firmware: 4.0.10.1288
- EC Firmware: 2.27
- PMC Firmware: v06.07.00
- Framework Reference Code: Based on 2.0.5

*Other names and brands may be claimed as the property of others.

- Integrated Graphics
- Option ROM: v13.0.1002
UEFI Driver: v13.0.1018
- LAN
Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Updated BIOS code for security fixes.
- Fixed issue where Secure Boot data cannot be cleared.
- Updated UEFI driver to version 13.0.1018.
- Updated CPU microcode to M01706A1_0000002C.
- Updated PMC firmware to version 06.07.00.
- Updated TXE firmware to version 4.0.10.1288.
- Changed RING LED to RGB LED in BIOS Setup to match motherboard silkscreen and Technical Product Specification.

Known Errata:

Due to the CPU microcode update in BIOS version 0049, you can't downgrade to version 0047 or earlier.

BIOS Version 0047 - JYGLKCPX.86A.0047.2018.1219.1246

About This Release:

- Date: December 19, 2018
- TXE Firmware: 4.0.0.1249
- EC Firmware: 2.27
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 2.0.3
- Integrated Graphics
- Option ROM: v13.0.1002
UEFI Driver: v13.0.1017
- LAN
Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Fixed issue where BIOS update via F7 fails if "SGX reserved memory size" is set to Auto.

BIOS Version 0046 - JYGLKCPX.86A.0046.2018.1103.1316

About This Release:

- Date: November 03, 2018
- TXE Firmware: 4.0.0.1249
- EC Firmware: 2.27
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 2.0.3
- Integrated Graphics
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.1017
- LAN
 - Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

*Other names and brands may be claimed as the property of others.

New Fixes/Features:

- Updated EC to 2.27
- Fixed the issue where an RC6 infrared remote would stop working in Linux.
- Fixed the MCE error reported in Linux.

BIOS Version 0045 - JYGLKCPX.86A.0045.2018.1001.1100

About This Release:

- Date: October 01, 2018
- TXE Firmware: 4.0.0.1249
- EC Firmware: 2.26
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 1.4.0
- Integrated Graphics
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.1017
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Fixed the issue where the system would hang if the startup sound was enabled.

BIOS Version 0044 - JYGLKCPX.86A.0044.2018.0821.1915

About This Release:

- Date: August 21, 2018
- TXE Firmware: 4.0.0.1249
- EC Firmware: 2.26
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 1.4.0
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.1017
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Updated TXE firmware to version 4.0.0.1249.
- Updated GOP to GOP_13.0.1017_20180817.

BIOS Version 0043 - JYGLKCPX.86A.0043.2018.0814.1104

About This Release:

- Date: August 14, 2018
- TXE Firmware: 4.0.0.1242
- EC Firmware: 2.26
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 1.4.0
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.1016

*Other names and brands may be claimed as the property of others.

- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Updated CPU Microcode (Security Advisory-00115)
- Updated help text for Setup item "Wake System from S5".
- Set Consumer Infrared default to disabled for Windows RS4 support.

BIOS Version 0042 - JYGLKCPX.86A.0042.2018.0718.1300

About This Release:

- Date: July 18, 2018
- TXE Firmware: 4.0.0.1242
- EC Firmware: 2.26
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 1.4.0
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.1016
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Fixed issue where TXE is not enabled when reinstalling security jumper.
- Removed Ready Mode related code/items in BIOS for Intel PSIRT fix.
- Due to a security enhancement, the BIOS cannot be downgraded to any version older than version 0042.

BIOS Version 0041 - JYGLKCPX.86A.0041.2018.0626.1500

About This Release:

- Date: June 26, 2018
- TXE Firmware: 4.0.0.1242
- EC Firmware: 2.26
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 1.4.0
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.1016
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Added BIOS option for GNA on the Onboard Devices page.
- Updated EC firmware to version 2.26.

BIOS Version 0039 - JYGLKCPX.86A.0039.2018.0528.1436

About This Release:

- Date: May 24, 2018

- TXE Firmware: 4.0.0.1242
- EC Firmware: 2.23
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 1.4.0
- Integrated Graphics:
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.1016
- LAN Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Added security enhancements.
- Fixed issue where Fault Tolerance failed when flashing BootBlock.
- Added setup item "Allow UEFI 3rd party driver loaded".

BIOS Version 0037 - JYGLKCPX.86A.0037. 2018.0423.1539
--

About This Release:

- Date: April 23, 2018
- TXE Firmware: 4.0.0.1242
- EC Firmware: 2.23
- PMC Firmware: v06.05.00
- Framework Reference Code: Based on 1.4.0
- Integrated Graphics
 - Option ROM: v13.0.1002
 - UEFI Driver: v13.0.1016
- LAN
 - Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Removed Legacy Boot Priority pane from BIOS Setup.
- Fixed issues with TPM Clear page.
- Fixed issue with Digital Microphone.
- Updated EC firmware to version 2.23.
- Fixed issue with SMBIOS Structure Types.
- Fixed issue with Unattended BIOS Configuration item.
- Updated PMC firmware to version 06.05.00.
- Updated TXE firmware to version 4.0.0.1242.
- Updated processor support.
- Fixed issue with HDD SMART and NVMe timeout.
- Fixed USB port issue.
- Updated GOP to version 13.0.1016.

BIOS Version 0027 - JYGLKCPX.86A.0027.2018.0125.1347

About This Release:

- Date: January 25, 2018
- TXE Firmware: 4.0.0.1235
- EC Firmware: 2.20
- PMC Firmware: v06.04.00
- Framework Reference Code: Based on 1.4.0
- Integrated Graphics:
 - Option ROM: v13.0.1002

*Other names and brands may be claimed as the property of others.

- o UEFI Driver: v13.0.1011
- LAN:
 - o Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Added Fortemedia audio driver support.
- Changed the default value of Intel® Smart Sound Technology from enabled to disabled.
- Fixed the issue that when the TPM message is cleared it causes the "Failsafe Watchdog" option to be enabled.
- Fixed the issue that when the CMOS is cleared it causes the recovery menu to be shown.
- Updated SMBIOS information.
- Updated processor support.
- Due to a security enhancement, it will not be possible to go to any BIOS earlier than BIOS 0027.

BIOS Version 0024 - JYGLKCPX.86A.0024.2017.1229.1454

About This Release:

- Date: December 29, 2017
- TXE Firmware: 4.0.0.1235
- EC Firmware: 2.20
- PMC Firmware: v06.04.00
- Integrated Graphics:
 - o Option ROM: v13.0.1002
 - o UEFI Driver: v13.0.1011
- LAN:
 - o Option ROM: PXE-2.1 BUILD (083) v2.66
- Visual Bios: 2.2.23

New Fixes/Features:

- Initial production BIOS release.

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

*Other names and brands may be claimed as the property of others.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2021 Intel Corporation.

*Other names and brands may be claimed as the property of others.