



BIOS Update Release Notes

**PRODUCTS: NUC5i3RYH, NUC5i3RYHS, NUC5i3RYHSN, NUC5i3RYK,
NUC5i5RYH, NUC5i5RYHS, NUC5i5RYK, NUC5i7RYH**

BIOS Version 0386 - RYBDWi35.86A.0386.2022.0705.1602

About This Release:

- Date: July 05, 2022
- ROM Image Checksum: 0X8B0A
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23
- Supported Flash Devices:

WinBond	W25Q64FV	8MB
MACRONIX	MX25L6406EM2I	8MB
- Microcode Updates included in .ROM & .BIO Files:
MC0306D4_0000002D

New Fixes/Features:

- Updated BIOS code for security fixes.

BIOS Version 0385 - RYBDWi35.86A.0385.2020.0519.1558

About This Release:

- Date: May 19, 2020
- ROM Image Checksum: 0X0A4E
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23

*Other names and brands may be claimed as the property of others.

- Supported Flash Devices:

WinBond	W25Q64FV	8MB
MACRONIX	MX25L6406EM2I	8MB
- Microcode Updates included in .ROM & .BIO Files:
MC0306D4_0000002D

New Fixes/Features:

- Updated BIOS code for security fixes.

BIOS Version 0384 - RYBDWi35.86A.0384.2020.0116.1708

About This Release:

- Date: Jan 16, 2020
- ROM Image Checksum: 0X8B0B
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23
- Supported Flash Devices:

WinBond	W25Q64FV	8MB
MACRONIX	MX25L6406EM2I	8MB
- Microcode Updates included in .ROM & .BIO Files:
MC0306D4_0000002D

New Fixes/Features:

- Updated BIOS code for security fixes.

BIOS Version 0383 - RYBDWi35.86A.0383.2019.1030.1528

About This Release:

- Date: October 30, 2019
- ROM Image Checksum: 0XC435
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23
- Supported Flash Devices:

*Other names and brands may be claimed as the property of others.

WinBond	W25Q64FV	8MB
MACRONIX	MX25L6406EM2I	8MB

- Microcode Updates included in .ROM & .BIO Files:
MC0306D4_0000002D

New Fixes/Features:

- Fixed issue where a custom splash screen can't be set using the Intel Integrator Toolkit.

BIOS Version 0382 - RYBDWi35.86A.0382.2019.1008.1130

About This Release:

- Date: October 8, 2019
- ROM Image Checksum: 0X822C
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23
- Supported Flash Devices:

WinBond	W25Q64FV	8MB
MACRONIX	MX25L6406EM2I	8MB
- Microcode Updates included in .ROM & .BIO Files:
MC0306D4_0000002D

New Fixes/Features:

- Fixed issue where UEFI Network PXE Boot option is not available.

BIOS Version 0381 - RYBDWi35.86A.0381.2019.0807.1532

About This Release:

- Date: August 7, 2019
- ROM Image Checksum: 0X437D
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23
- Supported Flash Devices:

WinBond	W25Q64FV	8MB
MACRONIX	MX25L6406EM2I	8MB
- Microcode Updates included in .ROM & .BIO Files:
MC0306D4_0000002D

New Fixes/Features:

- Updated BIOS code for security fixes.
- Improved BIOS code for USB module.

BIOS Version 0380 - RYBDWi35.86A.0380.2019.0517.1530

About This Release:

- Date: May 17, 2019
- ROM Image Checksum: 0X48AC
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Updated BIOS code for security fixes.
- Changed chassis enclosure type to 0x23.

Known Errata:

- Due to a security enhancement, it will not be possible to downgrade to BIOS 0366 or below.

BIOS Version 0379 - RYBDWi35.86A.0379.2019.0408.1945

About This Release:

- Date: April 8, 2019
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23

New Fixes/Features:

- Updated BIOS code for security fixes.

BIOS Version 0378 - RYBDWi35.86A.0378.2019.0219.1736

About This Release:

- Date: February 19, 2019
- ME Firmware: 10.0.45.1024

*Other names and brands may be claimed as the property of others.

- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23

New Fixes/Features:

- Updated BIOS code for security fixes.

BIOS Version 0377 - RYBDWi35.86A.0377.2018.1226.1750

About This Release:

- Date: December 26, 2018
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23

New Fixes/Features:

- Improved power limit and ICCmax settings.
- Added power limit setting for NUC5i5RYHS SKU.

BIOS Version 0375 - RYBDWi35.86A.0375.2018.1114.1652

About This Release:

- Date: November 14, 2018
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23

New Fixes/Features:

- Improved the thermal solution.
- Fixed issue where system hangs during POST when Western Digital 1TB MyPassport external USB drive is connected.

*Other names and brands may be claimed as the property of others.

- Added Setup item **Power Button Menu Beeps**, with default set to enabled.

BIOS Version 0373 - RYBDWi35.86A.0373.2018.0802.1639

About This Release:

- Date: August 2, 2018
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23

New Fixes/Features:

- BIOS functionality enhancements.
- Changed the naming scheme of the USB ports to more accurately denote where the port is on the board.

BIOS Version 0371 - RYBDWi35.86A.0371.2018.0709.1155

About This Release:

- Date: July 9, 2018
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Updated CPU Microcode (Security Advisory-00115)
- Disabled and removed Intel® Ready Mode Technology related items from BIOS setup for Intel Security fix.

BIOS Version 0370 - RYBDWi35.86A.0370.2018.0604.1034

About This Release:

- Date: June 04, 2018
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033

*Other names and brands may be claimed as the property of others.

- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Security enhancements.

BIOS Version 0369 - RYBDWi35.86A.0369.2018.0305.1050

About This Release:

- Date: March 05, 2018
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Updated CPU Microcode (Security Advisory-00088)

BIOS Version 0367 - RYBDWi35.86A.0367.2017.0929.1059

About This Release:

- Date: September 29, 2017
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Added Setup item "Allow UEFI 3rd party driver loaded" and set the default as disabled.
- Added security enhancements.
- Due to a security enhancement, it will not be possible to downgrade to any BIOS earlier than BIOS 0367.

BIOS Version 0366 - RYBDWi35.86A.0366.2017.0816.1026

About This Release:

- Date: August 16, 2017
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Added S.M.A.R.T item and functionality.

BIOS Version 0365 - RYBDWi35.86A.0365.2017.0704.1050

About This Release:

- Date: July 04, 2017
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Fixed issue where the screen wouldn't fit on some displays.

BIOS Version 0364 - RYBDWi35.86A.0364.2017.0511.0949

About This Release:

- Date: May 11, 2017
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23

New Fixes/Features:

- Fixed an issue where running TpmCreate.efi with the TPM_CC_Create command would cause an error message.

*Other names and brands may be claimed as the property of others.

- Fixed an issue when running CHIPSEC v1.2.5 would cause an error message.

BIOS Version 0362 - RYBDWi35.86A.0362.2017.0118.0940

About This Release:

- Date: January 18, 2017
- ME Firmware: 10.0.45.1024
- EC Firmware: NA
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- SATA RAID Option ROM: v14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on AHCI_09
- LAN Option ROM: v1553 PXE 2.1 Build 092
- Visual Bios: 2.2.23

New Fixes/Features:

- Security enhancements.

BIOS Version 0361 - RYBDWi35.86A.0361.2016.1202.1005

About This Release:

- Date: December 02, 2016
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Security Enhancements.

BIOS Version 0360 - RYBDWi35.86A.0360.2016.1109.0946

About This Release:

- Date: November 09, 2016
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Security Enhancements.

*Other names and brands may be claimed as the property of others.

- Changed SATA DevSleep default setting to disable.

BIOS Version 0359 - RYBDWi35.86A.0359.2016.0906.1028

About This Release:

- Date: September 06, 2016
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.23 Production Candidate Build

New Fixes/Features:

- Security Enhancements.
- Updated BootScriptHide module to BootScriptHide_02.
- Updated Visual BIOS to 2.2.23.
 - o Fixed missing voltages in Cooling Page.
 - o Fixed inactive Home Page 3 and Performance links on NUC theme.
 - o Added support for loading data from file for platform (e.g. EDID, Secure Boot, etc).
 - o Fixed issue where unsupported keys could be entered in password.
 - o Fixed hang when using keyboard to configure a drop down control.
 - o Added support for legacy boot options to Visual Boot Manager.
 - o Added support for booting to multiple partitions on the same device from Visual Boot Manager.
 - o Added support to Visual Boot Manager for booting to operating systems that do not support EFI default boot path.

BIOS Version 0358 - RYBDWi35.86A.0358.2016.0606.1423

About This Release:

- Date: June 06, 2016
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.20 Production Candidate Build

New Fixes/Features:

- Fixed an issue that when the Visual BIOS theme was changed to VISUAL_BIOS_THEME_TYPE = 0 (PERFORMANCE_THEME) it wouldn't show

Fan Speeds, Temperatures, and Thresholds icons in Performance Monitor item of the Setup Home page.

- Fixed an issue where the NUC can't wake up from S3 by pressing the power button in Linux.
- Added Windows Update patch.

Visual BIOS update to 2.2.20. Fixes include:

- Hotfix to remove performance page accessibility from Atom-based NUC products.
- Hotfix to remove download driver and automatic BIOS update feature.

BIOS Version 0356 - RYBDWi35.86A.0356.2016.0506.1355

About This Release:

- Date: May 09, 2016
- ME Firmware: 10.0.45.1024
- Memory Reference Code: Based on 2.9.0
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.17 Production Candidate Build

New Fixes/Features:

- Hid "NFC" setup item.
- Improved BIOS update function to disable keyboard and power button during flash/recovery process.
- Removed WlanDynamicSolution setup item but kept WiFi WRDD.
- Improved power button menu and F4 recovery by:
 - o Removing the G3 power button recovery
 - o Adding BIOS ID information prompt
 - o Allowing the user to cancel the recovery by selecting [ESC] within 20 seconds of starting the process
 - o Added progress information during the recovery.
 - o Increased the key press detection to 3.51 sec.
- Updated Visual BIOS to 2.2.20.
- Hotfix to remove download driver and automatic BIOS update feature.

BIOS Version - RYBDWi35.86A.0355.2016.0224.1501
--

About This Release:

- Date: February 25, 2016
- ME Firmware: 10.0.45.1024
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.17 Production Candidate Build

New Fixes/Features:

- Fixed issue where NVMe m.2 would not be seen in Windows 7.
- Fixed issue where the user could access Failsafe watchdog when the User Password and User Access Level was not set for access.

BIOS Version - RYBDWi35.86A.0354.2016.0120.0912
--

About This Release:

- Date: January 20, 2016
- ME Firmware: 10.0.45.1024
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.17 Production Candidate Build

New Fixes/Features:

- Fixed an issue with secure boot and PXE security.
- Fixed an issue where Intel Tool Kit showed the incorrect project name.
- Fixed an issue where the user could access the Cooling page when the user access was set to Limited.

BIOS Version 0353 - RYBDWi35.86A.0353.2015.1222.0947

About This Release:

- Date: December 22, 2015
- ME Firmware: 10.0.45.1024
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.17 Production Candidate Build

New Fixes/Features:

- Fixed issue where Ctrl + I wouldn't show, so it wasn't possible to configure RAID.
- Fixed issue where SMBIOS TYPE9 wouldn't fill in the correct information.
- Fixed issue that would cause Device Manager to show "unknown device" when CIR was disabled in BIOS.

BIOS Version 0352 - RYBDWi35.86A.0352.2015.1130.1011

About This Release:

- Date: November 30, 2015
- ME Firmware: 10.0.45.1024
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN

- Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.17 Production Candidate Build

New Fixes/Features:

- Fixed an issue where the BIOS settings aren't saved after flash update.

BIOS Version 0350 - RYBDWi35.86A.0350.2015.0812.1722

About This Release:

- Date: August 12, 2015
- ME Firmware: 10.0.45.1024
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.17 Production Candidate Build

New Fixes/Features:

- Fixed issue where system does not wake up from S5 using USB devices when BIOS option for **Wake on LAN from S4/S5** is set to **Stay Off**.
- Fixed issue where audio corruption occurs in Windows 7.
- Updated Visual BIOS to version 2.2.17. Fixes include:
 - Refactored graphics resolution algorithm to find closest supported resolution to 1024x768. This should correct scaling issues with 4K monitors.
 - Removed unused assets from Performance and Mainstream themes to reduce the overall size of Visual BIOS. Size savings should be around 300KB.

BIOS Version 0348 - RYBDWi35.86A.0348.2015.0703.1124

About This Release:

- Date: July 3, 2015
- ME Firmware: 10.0.45.1024
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5. 1033
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v14.5.0.2241
- Visual Bios: 2.2.16 Production Candidate Build

NOTE: Audio corruption in Windows 7 can occur with this BIOS version. Windows 10 and Windows 8.1 do not have any audio corruption issues with this BIOS version. Intel recommends that Windows 7 users upgrade to BIOS version 0350.

New Fixes/Features:

- Updated VBIOS to version 1039
- Updated GOP to version 1033.
- Updated Intel® ME firmware to version 10.0.45.1024.

*Other names and brands may be claimed as the property of others.

- Updated processor support.
- Updated RAID Option ROM to version 14.5.0.2241.
- Fixed issue where the power button on certain remote control does not wake the computer.
- Fixed issue where USB mouse and keyboard do not work as expected in BIOS setup.

BIOS Version 0249 - RYBDWi35.86A.0249.2015.0529.1640

About This Release:

- Date: May 29, 2015
- ME Firmware: 10.0.38.1000
- Integrated Graphics
 - Option ROM: Build 1038_150303
 - UEFI Driver: 5.5. 1032_150303
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v13.5.0.2164
- Visual Bios: 2.2.16 Production Candidate Build

New Fixes/Features:

- Fixed issue where SMBIOS system manufacturer and system model are incorrect in MSINFO32 and other applications.
- Fixed issue where the Event Log does not display an error when the battery is removed.
- Fixed issue where the watchdog timer fails to reboot the system after a system hang.
- Added BIOS option in Intel® Integrator Toolkit (ITK) to Install Intel Platform Key.
- Updated UQI and ITK items:
 - o Correct UQIs with setup spec v0.97.
 - o Show "Balanced Enabled", "Low power enabled" and "Max performance enabled" in ITK GUI.
 - o Show the power page sub-items in ITK GUI. (PL1/PL2/ICC Max/Tau/EIST/OS ACPI C2)

BIOS Version 0247 - RYBDWi35.86A.0247.2015.0415.1351

About This Release:

- Date: April 15, 2015
- ME Firmware: 10.0.38.1000
- Integrated Graphics
 - Option ROM: Build 1038_150303
 - UEFI Driver: 5.5. 1032_150303
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v13.5.0.1056
- Visual Bios: 2.2.16 Production Candidate Build

New Fixes/Features:

- Added BIOS options on the Secondary Power Settings page to enable or disable Wake from S3 via CIR and Wake from S4 and S5 via CIR.
- Added BIOS option on the Legacy Device Config page to select the CIR Remote Controller Type.
- Fixed issue where CIR remote fails in OpenELEC*.

*Other names and brands may be claimed as the property of others.

- Fixed issue where SMBIOS System Manufacturer and System Model do not appear correctly in MSINFO32 and other applications.
- Updated help string of USB charging port: *Charging Only: USB Port will always provide extra power but cannot be used to transfer data with USB 2.0 device.*

BIOS Version 0246 - RYBDWi35.86A.0246.2015.0309.1355

About This Release:

- Date: March 9, 2015
- ME Firmware: 10.0.38.1000
- Integrated Graphics
 - Option ROM: Build 1038_150303
 - UEFI Driver: 5.5. 1032_150303
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v13.5.0.1056
- Visual Bios: 2.2.16

New Fixes/Features:

- Added performance settings for NUC5i7RYH SKU.
- Updated Intel® ME firmware to version 10.0.38.1000.
- Updated GOP to version 1032 and vBIOS to version 1038.
- Updated processor support.
- Added xHCI Mode setting to USB Configuration page in BIOS.
- Fixed issue with ISCSI IPV6.
- Fixed issue where loading default values fails.
- Fixed WHCK TPM issues:
 - BitLocker Tpm+PIN+ USB and Recovery Password tests for NON ARM devices
 - TPM 2.0 - Supplemental test
 - TPM 2.0 UEFI Preboot Interface Test
 - TPM Platform Crypto Provider Key Storage Provider Test
- Added support for M.2 PCIe NVMe storage boot.
- Updated Intel® Visual BIOS to version 2.2.16. Fixes include:
 - Fixed issue in Download Drivers feature where certain drivers were not visible if multiple attachments exist in the same record.
 - Fixed issue in Download Drivers feature where incorrect drivers would display if product was not found in database.
 - Fixed issue in Performance page that prevented additional workspaces from showing up (i.e. Memory Timings, etc.)
- Added support for F5 Windows Recovery feature.
- Fixed issue where system hangs at POST code 19 after Intel Platform Trust Technology is enabled.
- Fixed issue where VT-d is missing from BIOS.
- Modified NFC behavior: When NFC is enabled in BIOS, GPIO Lockdown is disabled and greyed out.
- Fixed issue with Fixed Disk Boot Sector.
- Modified the options for the IGD Aperture size setting.
- Added WLAN and Bluetooth settings to the Onboard Devices page in BIOS.
- Fixed issue where BIOS password prompts are not suppressed in Config Mode.

*Other names and brands may be claimed as the property of others.

BIOS Version 0137 - RYBDWi35.86A.0137.2015.0107.1700

About This Release:

- Date: January 7, 2015
- ME Firmware: 10.0.30.1072
- Integrated Graphics
 - Option ROM: Build 1035_1103
 - UEFI Driver: 5.5.1031_1103
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v13.5.0.1056
- Visual Bios: 2.2.14 Production Candidate Build

New Fixes/Features:

- Fixed issue where customized power setting options are missing.
- Fixed issue where ICC Max is hidden if any pre-defined power settings are enabled.
- Fixed issue where BIOS password prompts are not suppressed in Config Mode.
- Fixed issue where VCUST and Intel® Integrator Toolkit cannot access the Near Field Communication BIOS option.
- Added onboard WiFi and Bluetooth* setup items in BIOS Setup.
- Updated BIOS to hide Power page items if Low Power, Balanced Power, or Max Performance is enabled.
- Updated processor support.
- Fixed issue where an error on NFC device shows in Device Manager.
- Fixed issue where Onboard LAN as the first boot device will fail.
- Updated Visual BIOS to version 2.2.14. Fixes include:
 - Fixed touch monitors not working correctly when display adapter supports greater than 1024x768 resolution.
 - Fixed AMT USB-R issue where absolute mouse position would not scale correctly in Visual BIOS.
- Added "Power Sense" item.

BIOS Version 0132 - RYBDWi35.86A.0132.2014.1217.1148

About This Release:

- Date: December 17, 2014
- ME Firmware: 10.0.30.1072
- Integrated Graphics
 - Option ROM: Build 1032_1006
 - UEFI Driver: 5.5.1028_1006
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v13.5.0.1056
- Visual Bios: 2.2.13

New Fixes/Features:

- Set SIO GPIO 76 output Low.
- Fixed issue where it takes too long to begin a flash update.
- Fixed issue where system shuts down when LAN is disabled in BIOS.
- Added GPIO lockdown item in BIOS.

BIOS Version 0130 - RYBDWi35.86A.0130.2014.1203.1639

About This Release:

- Date: December 3, 2014
- ME Firmware: 10.0.30.1072
- Integrated Graphics
 - Option ROM: Build 1032_1006
 - UEFI Driver: 5.5.1028_1006
- LAN
 - Option ROM: v1553 PXE 2.1 Build 092
- SATA RAID Option ROM: v13.5.0.1056
- Visual Bios: 2.2.13

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2015 Intel Corporation.