# Release Notes Intel® Killer Performance Suite 35.23.1292



# **Supported Operating Systems**

Microsoft Windows 10° and Windows 11° (64 Bit only)

# **Supported Products and Driver Versions**

Intel® Wireless Adapter	Windows 10	Windows 11
Intel® Killer Wireless-AC 1550	23.20.0.4	
Intel® Killer Wi-Fi 6 AX1650		
Intel® Killer Wi-Fi 6e AX1675		
Intel® Killer Wi-Fi 6e AX1690		
Intel® Killer E3100 2.5Gb Ethernet	1.1.4.42	2.1.3.15
Intel® Killer E3100x 2.5 Gb Ethernet		
Intel® Killer E5000 Ethernet	10.68.815.2023	1126.016.1123.2023
Killer E3000 2.5Gb Ethernet	10.68.815.2023	1125.15.717.2023
Killer E3100G 2.5Gb Ethernet		
Killer E2500v2 1Gb Ethernet	10.68.815.2023	1168.15.717.2023
Killer E2600 1Gb Ethernet		
Killer Networking Software	3.1523.1205.1	

Note: This Software Release version does not include new drivers for the Killer E2200, Killer E2400, Killer E2500, Killer 1525 Wireless, Killer 1535 Wireless, Killer 1435 Wireless, or the Killer AX500 Wireless adapters, but the Killer Networking Software can be installed on the systems with the above adapters.



# Key Issues Fixed and Changes: Package Version 35.23.1292

#### Description of Key Issue

Updated Wi-Fi driver to version 23.20.0.4

Updated E5000 driver to version 1126.016.1123.2023

Note: Key issues fixed in the OS indicated in the table above

## Key Issues Fixed and Changes: Package Version 23.20.0.4

Description of Key Issue	OS
Crashes occurring during heavy network loads	Win10/Win11
Peer-to-peer connection with Samsung Fold 5 suddenly disconnects	Win10/Win11
"No Wi-Fi Networks found" on connection/disconnection from Miracast Bluetooth headset	Win10/Win11
Enable WiFi 6E band in Taiwan	Win10/Win11
Power management based on network latency	Win10/Win11

Note: Key issues fixed in the OS indicated in the table above

### Key Issues Fixed and Changes: Killer software 3.1523.1205.1

#### Description of Key Issue

Message "Bandwidth Not Set" is only displayed when auto bandwidth is disabled

Manual input limit updated from 2.5 gbps to 15 in Speedtest

Note: Key issues fixed in the OS indicated in the table above

#### **Legal Notices**

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.



Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visithttp://www.intel.com/performance.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting <a href="https://www.intel.com/design/literature.htm">www.intel.com/design/literature.htm</a>.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

©February 2021 Intel Corporation.

