

# Release Notes

# Intel® PROSet/Wireless Software 23.30.0

#### **Important Notice**

• This software package includes drivers for Intel® Wi-Fi 7 products\* - Intel® Wi-Fi 7 BE202 and Intel® Wi-Fi 7 BE200 (\*please see Notes below).

### **Supported Operating Systems**

Microsoft Windows® 10 and Microsoft Windows 11\*

(Notes. Starting with Software Release 21.50.1, there will be no new driver versions for Windows\*7 and Windows\* 8.1 Operating Systems.)

### **Supported Products and Driver Versions**

Intel® Wireless Adapter	Windows 11* Windows® 10	Windows* 8.1	Windows* 7
Intel® Wi-Fi 7 BE202 Intel® Wi-Fi 7 BE200 Intel® Wi-Fi 6E AX411 (Gig+) Intel® Wi-Fi 6E AX211 (Gig+) Intel® Wi-Fi 6E AX210 (Gig+) Intel® Wi-Fi 6 AX203 Intel® Wi-Fi 6 AX201 Intel® Wi-Fi 6 AX200 Intel® Wi-Fi 6 AX101 Intel® Wireless-AC 9560 Intel® Wireless-AC 9461/ 9462 Intel® Wireless-AC 9260	23.30.0.6 <sup>1</sup>	n/a	n/a
Intel® Dual Band Wireless-AC 3168 Intel® Dual Band Wireless-AC 3165 Intel® Wireless 7265 Family (Rev.D)	64-bit: 19.51.50.2 32-bit: 19.51.40.1 <sup>2</sup>	19.10.21.1	19.10.21.1

**Notes.** From the release 22.220.0 package onwards, this software no longer includes drivers for <u>discontinued</u> wireless products: Intel® Dual Band Wireless-AC 8260 and Intel® Dual Band Wireless-AC 8265. For 8260 and 8265 Wi-Fi drivers, see <u>Intel® Wireless Wi-Fi Drivers for Intel® Dual Band Wireless-AC 8260 and Intel® Dual Band Wireless-AC 8265</u>.

<sup>&</sup>lt;sup>1</sup>64-bit only

<sup>2</sup> 32-bit drivers available for Windows® 10 will only receive updates to address potential security vulnerabilities from version 22.170.x package onwards. Last available Win10 32-bit driver version is 19.51.40.1 from package 22.160.0

#### Notes

- For the new Intel® Wi-Fi 7 products Intel® Wi-Fi 7 BE202 and Intel® Wi-Fi 7 BE200
  - All Intel® Wi-Fi 7 products support the 6GHz band for Wi-Fi. Usage of the 6GHz band relies
    on Microsoft Windows (Windows 11\*) Operating System support. The products have
    limited functionality on Windows® 10.
  - The Wi-Fi 7 features are not currently available because of pending OS (Windows 11\*) support. As a result, after installing the drivers, the Intel® Wi-Fi 7 products function with Wi-Fi 6E capabilities on Windows 11\*.
- The Intel's Wi-Fi 7 product "Intel® Wi-Fi 7 BE200" will support Wi-Fi 6E + 320 MHz/4K QAM (known as EHT Extremely High Throughput) by default when connecting to a Wi-Fi 7 wireless router/AP.

## Key Issues Fixed and Changes: Package Version 23.30.0

Description of Key Issue	os
Enhanced QoS Management	Win10/Win11
Enhanced Power Management based on network latency	Win10/Win11
Regulatory updates for Taiwan, Bahrain, China, Japan, and South Korea	Win10/Win11
On some systems, blue screen might occur which are associated the Intel Wireless driver.	Win10/Win11
On some systems, Windows System Event ID 5002 might occur after resuming from Standby mode.	Win10/Win11
When lid on some systems, the wireless adapter may stop working and show a yellow bang in Device Manager.	Win10/Win11
On some systems, Wi-Fi list might show "No Wi-Fi networks found" when connecting to wireless AP.	Win10/Win11
On some systems, wireless adapter couldn't connect the monitor via Miracast.	Win10/Win11
This software release version 23.30.0 has been updated to include functional supdates. There	Win10/Win11
may be other minor issues addressed which will impact performance, stability, or vendor specific functionality not listed above. Users should update to the latest version.	

#### **Legal Notices**

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <a href="http://www.intel.com/performance">http://www.intel.com/performance</a>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting <a href="https://www.intel.com/design/literature.htm">www.intel.com/design/literature.htm</a>.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

©Feb 2024 Intel Corporation.