



Release Notes

Intel® Killer Performance Suite 35.24.1177

Supported Operating Systems

Microsoft Windows 10® and Windows 11® (64 Bit only)

Supported Products and Driver Versions

Intel® Wireless Adapter	Windows 10	Windows 11
Intel® Killer Wireless-AC 1550	23.30.0.6	
Intel® Killer Wi-Fi 6 AX1650		
Intel® Killer Wi-Fi 6e AX1675		
Intel® Killer Wi-Fi 6e AX1690		
Intel® Killer E3100 2.5Gb Ethernet	1.1.4.42	2.1.3.15
Intel® Killer E3100x 2.5 Gb Ethernet		
Intel® Killer E5000 Ethernet	10.68.815.2023	1126.016.1123.2023
Killer E3000 2.5Gb Ethernet	10.68.815.2023	1125.15.717.2023
Killer E3100G 2.5Gb Ethernet		
Killer E2500v2 1Gb Ethernet	10.68.815.2023	1168.15.717.2023
Killer E2600 1Gb Ethernet		
Killer Networking Software	3.1524.121.1	

Note: This Software Release version does not include new drivers for the Killer E2200, Killer E2400, Killer E2500, Killer 1525 Wireless, Killer 1535 Wireless, Killer 1435 Wireless, or the Killer AX500 Wireless adapters, but the Killer Networking Software can be installed on the systems with the above adapters.



Key Issues Fixed and Changes: Package Version 35.24.1177

Description of Key Issue
Updated Wi-Fi driver to version 23.30.0.6

Note: Key issues fixed in the OS indicated in the table above

Key Issues Fixed and Changes: Package Version 23.30.0.6

Description of Key Issue	OS
Enhanced QoS Management	Win10/Win11
Enhanced Power Management based on network latency	Win10/Win11
Regulatory updates for Taiwan, Bahrain, China, Japan, and South Korea	Win10/Win11
On some systems, blue screen might occur which are associated the Intel Wireless driver.	Win10/Win11
On some systems, Windows System Event ID 5002 might occur after resuming from Standby mode.	Win10/Win11
On some systems, the wireless adapter may stop working and show a yellow bang in Device Manager.	Win10/Win11
On some systems, Wi-Fi list might show "No Wi-Fi networks found" when connecting to wireless AP.	Win10/Win11
On some systems, wireless adapter couldn't connect to the monitor via Miracast.	Win10/Win11
This software release version 23.30.0 has been updated to include functional updates. There may be other minor issues addressed which will impact performance, stability, or vendor specific functionality not listed above. Users should update to the latest version.	Win10/Win11

Note: Key issues fixed in the OS indicated in the table above

Key Issues Fixed and Changes: Killer software 3.1524.121.1

Description of Key Issue
Support for WiFi Multi-Link Devices (MLD)
Smart AP disabled due to Windows subsystem for Android

Note: Key issues fixed in the OS indicated in the table above

Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.



Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

©February 2021 Intel Corporation.

