

Release Notes

Intel® Wireless Bluetooth® 24.30.1 for IT Administrators

Package Version and Supported Operating Systems	24.30.1 for: Microsoft Windows® 10 and Microsoft Windows 11*
---	--

Supported Products and Driver Versions

Intel® Wireless Adapter	Windows® 10 Windows 11*
Intel® Wi-Fi 7 BE213	24.30.1.1 ¹
Intel® Wi-Fi 7 BE211	
Intel® Wi-Fi 7 BE202	
Intel® Wi-Fi 7 BE201	
Intel® Wi-Fi 7 BE200	
Intel® Wi-Fi 6E AX411	
Intel® Wi-Fi 6E AX211	
Intel® Wi-Fi 6E AX210	
Intel® Wi-Fi 6 AX203	
Intel® Wi-Fi 6 AX201	
Intel® Wi-Fi 6 AX101	
Intel® Wireless-AC 9560	
Intel® Wireless-AC 9462	
Intel® Wireless-AC 9461	
Intel® Wireless-AC 9260	

Notes.

IMPORTANT!

For PCs with Intel® Wireless-AC 9560, Intel® Wireless-AC 9462, Intel® Wireless-AC 9461: Before Upgrading from 23.10.x.x - 23.50.x.x versions to this 24.30.1 driver, the user needs to disconnect all the Bluetooth® devices and unpair all the previously paired devices in the PC. Once upgrade is complete, the user can repair the devices and connect them. Fixes for PCs with Bluetooth® drivers prior to 23.10.0 can be upgraded to 24.30.1.

From the release 24.20.0 package onwards, this software no longer includes drivers for discontinued products Intel® Wi-Fi 6 AX200, Intel® Wi-Fi 6 (Gig+) Desktop Kit and Intel® Killer™ Wi-Fi 6 AX1650(x/w) Bluetooth® drivers, see [Intel® Wireless Bluetooth® drivers for Intel® Wi-Fi 6 AX200 Bluetooth® drivers](#)

From the release 23.50.0 package onwards, this software no longer includes drivers for discontinued products Intel® Dual Band Wireless-AC 7265 (Rev. D), Intel® Dual Band Wireless-AC 3168 and Intel® Wireless-AC 3165. For 7265 (Rev. D), 3168 and 3165 Bluetooth® drivers, see [Intel® Wireless Bluetooth® Drivers for Wireless Products 7265\(Rev. D\), 3168 and 3165.](#)

From the release 22.210.0 package onwards, this software no longer includes drivers for discontinued wireless products: Intel® Dual Band Wireless-AC 8260 and Intel® Dual Band Wireless-AC 8265. For 8260 and 8265 Bluetooth® drivers, see [Intel® Wireless Bluetooth® Drivers for Intel® Dual Band Wireless-AC 8260 and Intel® Dual Band Wireless-AC 8265](#)

¹ 64-bit only

Key Changes in 24.30.1

Intel® Wireless Bluetooth® 24.30.1 driver has been updated to include functional updates. Users are encouraged to update to the latest version for best performance.

Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

© Mar 2026 Intel Corporation.