

Release Notes

Intel® Killer Performance Suite 40.26.220.2126

Supported Operating Systems

Microsoft Windows 10 x64 and Windows 11

Supported Products and Driver Versions

<i>Intel® Wireless Adapter</i>	<i>Windows 10 x64</i>	<i>Windows 11</i>
Intel® Killer Wi-Fi 7 BE1775	24.30.1.1	
Intel® Killer Wi-Fi 7 BE1750		
Intel® Killer Wi-Fi 6E AX1690		
Intel® Killer Wi-Fi 6E AX1675		
Intel® Killer Wi-Fi 6 AX1650 (i/s)		
Intel® Killer Wireless-AC 1550		
Intel® Killer E3100 2.5Gb Ethernet	1.1.4.45	2.1.5.7
Intel® Killer E3100x 2.5Gb Ethernet		
Intel® Killer E5000 Ethernet	10.79.50.1003	1126.27.50.919
Killer E3000 2.5Gb Ethernet	10.79.50.1003	1125.27.50.919
Killer E3100G 2.5Gb Ethernet		
Killer E2500v2 1Gb Ethernet	10.79.50.1003	1168.27.50.919
Killer E2600 1Gb Ethernet		
Killer Performance Suite Software	40.26.220.212	

Notes

- From the release of 40.26.220.2126 package onwards, this software no longer includes drivers for discontinued products, Intel® Killer™ Wi-Fi 6 AX1650 (x/w) Wireless drivers, see [Intel® Killer™ Performance Suite drivers for Intel® Killer™ Wi-Fi 6 AX1650 \(x/w\)](#).
- This software release does not include new drivers for the Killer E2200, Killer E2400, Killer E2500, Killer 1525 Wireless, Killer 1535 Wireless, Killer 1435 Wireless, or the Killer AX500 Wireless adapters, but the Killer Performance Suite Software can be installed on the systems with the above adapters.
- Some drivers from this package may not have been updated and are the same as the previous package. Please install this package to ensure all drivers are current.

Installation Updates

<i>Description of Update</i>
Updated Wi-Fi driver to version 24.30.1.1
Killer Performance Suite - Software Version 40.26.220.212

Killer Performance Suite v40.26.220.2126 - Key Issues Fixed and Changes

<i>Description of Key Issue</i>
Missing axis labels in Optimizations tab.
Fixed crash caused by settings desynchronization in Wi-Fi Analyzer.
In DoubleShot Pro, resolved the text alignment.

Note: Key issues fixed in the OS indicated on the table above

Wi-Fi Driver v24.30.1.1 - Key Issues Fixed and Changes

<i>Description of Key Issue</i>	<i>OS</i>
Since release 24.30.1, this package no longer includes drivers for discontinued Intel® Wi-Fi 6 AX200.	Win10/Win11
Better wireless stability and connect performance.	Win10/Win11
Regulatory updates for Oman, Russia, Brazil and Pakistan.	Win10/Win11
This software released version 24.30.1 has been updated to include functional and security updates. There may be other minor issues addressed which will impact performance, stability, or vendor specific functionality not listed above. <u>Users are encouraged to update to the latest version for best performance.</u>	Win10/Win11

Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

© Mar 2026 Intel Corporation.