



# **Intel® Desktop Board D845GLLY Product Supplement Specification Update**

Release Date: November 2003

Order Number: A98275-009

The Intel® Desktop Board D845GLLY may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are documented in this Specification Update.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. INTEL PRODUCTS ARE NOT INTENDED FOR USE IN MEDICAL, LIFE SAVING, LIFE SUSTAINING APPLICATIONS.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel® desktop board D845GLLY may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation  
P.O. Box 5937  
Denver, CO 80217-9808

or call in North America 1-800-548-4725, Europe 44-0-1793-431-155, France 44-0-1793-421-777,  
Germany 44-0-1793-421-333, other Countries 708-296-9333

Intel, Pentium, Celeron, and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\* Other names and brands may be claimed as the property of others.

Copyright © 2002, 2003, Intel Corporation. All rights reserved.

# CONTENTS

REVISION HISTORY .....v

PREFACE .....vi

**Product Supplement Specification Update for the Intel® Desktop Board D845GLLY**

GENERAL INFORMATION .....3





## REVISION HISTORY

Date of Revision	Version	Description
June 2002	-001	This document is the first Product Supplement Specification Update for the Intel® Desktop Board D845GLLY.
August 2002	-002	Updated General Information Section. Removed Printed Board Assembly (PBA) information from the document, as this reference is no longer valid.
September 2002	-003	Updated General Information Section. Updated Legal Disclaimer Section.
October 2002	-004	Added Specification Changes 1, 2. Added Erratum 2.
February 2003	-005	Updated Chipset Stepping. Added Specification Changes 4-8 to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order Number A98269). Added Errata 3. Added Specification Clarification 1.
March 2003	-006	Added Erratum 4. Added Documentation Changes 3, 4.
April 2003	-007	Added Documentation Change 5.
July 2003	-008	Added Specification Change 9.
November 2003	-009	Added Specification Clarification 2.

## PREFACE

This document is an update to the specifications contained in the *Intel® Desktop Board D845GLLY Product Supplement Document* (Order number A86194). It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It will contain Specification Changes, Errata, Specification Clarifications, and Documentation Changes.

Refer to the *Intel® Pentium® 4 Processor Specification Update* (Order number 249199) for specification updates concerning the Intel Pentium 4 processor and that may apply to the desktop board D845GLLY. Unless otherwise noted in this document, it should be assumed that any processor errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Refer to the *Intel® 845 Chipset: 82845 Memory Controller Hub (MCH) Specification Update* (Order Number 298589) for specification updates concerning the 82845GL MCH Controller and that may apply to the desktop board D845GLLY. Unless otherwise noted in this document, it should be assumed that any MCH errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Refer to the *Intel® 82801DB I/O Controller Hub 4 (ICH4) Specification Update* (Order Number 290745) for specification updates concerning the 82801DB I/O Controller Hub and that may apply to the desktop board D845GLLY. Unless otherwise noted in this document, it should be assumed that any 82801DB I/O Controller Hub (ICH) errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

## Nomenclature

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

**Errata** are design defects or errors. Characterized errata may cause the desktop board D845GLLY's behavior to deviate from published specifications. Hardware and software designed to be used with any given Altered Assembly (AA) and BIOS revision level must assume that all errata documented for that AA and BIOS revision level are present on all desktop boards.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

**Product Supplement Specification Update for the  
Intel® Desktop Board D845GLLY**





## GENERAL INFORMATION

Basic Desktop Board D845GLLY Identification Information

AA Revision	BIOS Revision	Notes
A84242-203	LY84510A.86A.0007.P01	1-5
A84242-204	LY84510A.86A.0008.P02	1-5
A84242-205	LY84510A.86A.0009.P03	1-5
A84242-206	LY84510A.86A.0011.P05	1-5
A84242-207	LY84510A.86A.0011.P05	1-5
A84242-208	LY84510A.86A.0022.P08	1-5
A84242-209	LY84510A.86A.0023.P09	1-5
A84242-210	LY84510A.86A.0029.P11	1-5
A84242-211	LY84510A.86A.0038.P15	1-5
A84741-203	LY84510A.86A.0009.P03	1-5
A84741-204	LY84510A.86A.0011.P05	1-5
A84741-205	LY84510A.86A.0011.P05	1-5
A84741-206	LY84510A.86A.0022.P08	1-5
A84741-207	LY84510A.86A.0023.P09	1-5
A84741-208	LY84510A.86A.0029.P11	1-5
A84741-209	LY84510A.86A.0038.P15	1-5
A86719-201	LY84510A.86A.0008.P02	1-5
A86719-202	LY84510A.86A.0009.P03	1-5
A86719-203	LY84510A.86A.0011.P05	1-5
A86719-204	LY84510A.86A.0011.P05	1-5
A86719-205	LY84510A.86A.0022.P08	1-5
A86719-206	LY84510A.86A.0023.P09	1-5
A86719-207	LY84510A.86A.0023.P09	1-5
A86719-208	LY84510A.86A.0038.P15	1-5
A86723-203	LY84510A.86A.0008.P02	1-5
A86723-204	LY84510A.86A.0009.P03	1-5
A86723-205	LY84510A.86A.0011.P05	1-5
A86723-206	LY84510A.86A.0011.P05	1-5
A86723-207	LY84510A.86A.0022.P08	1-5

## Basic Desktop Board D845GLLY Identification Information (cont)

AA Revision	BIOS Revision	Notes
A86723-208	LY84510A.86A.0023.P09	1-5
A86723-209	LY84510A.86A.0029.P11	1-5
A86723-210	LY84510A.86A.0038.P15	1-5

## NOTES:

1. The AA number is found on a small label on the component side of the board.
2. The 82845GL Chipset kit used on this AA revision consists of three components as follows:

Device	Stepping	S-Spec Numbers
82845GL GMCH	A1 B1	SL66G SL6PT
82801DB ICH	A1 B0	SL66K SL6DM
82802AB FWH	A1	SB48

3. Refer to the *Intel® Pentium® 4 Processor Specification Update* (Order Number 249199) for errata related to the Pentium 4 processor and that may apply to the desktop board D845GLLY.
4. Refer to the *Intel® 845 Chipset: 82845 Memory Controller Hub (MCH) Specification Update* (Order Number 298589) for errata related to the 82850/82850E MCH that may apply to the desktop board D845GLLY.
5. Refer to the *Intel® 82801DB I/O Controller Hub 4 (ICH4) Specification Update* (Order Number 290745) for errata related to the 82801DB I/O Controller Hub that may apply to the desktop board D845GLLY.



## Summary Table of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications, or Documentation Changes that apply to the desktop board D845GLLY. Intel intends to fix some of the errata in a future revision of the desktop board, and to account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

### CODES USED IN SUMMARY TABLE

Doc:	Document change or update that will be implemented.
PlanFix:	This erratum may be fixed in a future revision of the desktop board, driver, or BIOS.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Shaded:	This erratum is either new or modified from the previous version of the document.

NO.	PLANS	SPECIFICATION CHANGES
1	Doc	Refer to the <i>Intel® Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
2	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
3	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
4	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
5	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
6	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
7	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
8	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
9	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
NO.	PLANS	ERRATA
1	Fixed	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this erratum.
2	Fixed	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this erratum.
3	PlanFix	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this erratum.
4	PlanFix	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this erratum.



NO.	PLANS	SPECIFICATION CLARIFICATIONS
1	Doc	Refer to the <i>Intel® Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification clarification
2	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification clarification
NO.	PLANS	DOCUMENTATION CHANGES
1	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
2	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
3	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
4	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change
5	Doc	Refer to the <i>Intel Desktop Board 845GL Chipset Family Specification Update</i> (Order number (A98269) for this specification change