



BIOS Update Release Notes

PRODUCTS: DP35DP, DG33TL, DG33BU, DG33FB (Standard BIOS)

BIOS Version 0413

About This Release:

- March 06, 2008
- DPP3510J.86A. 0413.2008.0306.2218
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.6.0.1011
- SATA AHCI info:
Version UPSD src 12-03-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build QST_3.2.0.1018.

New Fixes/Features:

- Fixed BIOS update current to current.
- Fixed SATA AHCI Hot-Plug from the Intel Matrix Storage Manager driver.
- Updated Intel(R) ME Firmware to 3.2.0.1018.
- iQST: Fan detection improvement.
- Fixed F9 load default changed Wake on LAN from S5 option while it is grayed out.
- Fixed pressing the power button for more than 4 sec does not power off the PC.
- Fixed EIT/VA process data overwriting Interrupt vector table.
- Removed pre-production ME Firmware from BIOS update capsule.
- Added support to select the appropriate voltage based on CPU and FSB speed.
- Updated Txt Ac modules.
- Fix for TXT Bios_OS_Data reporting.
- Update TXT Heap BIOS_OS_DATA.
- TXT Fix for GetSec SCHECK.
- Change VT-d Tables for Txt.
- Fixed the incorrect naming "+3.3v" in Hardware Monitoring Page, "+3.3v Standby" will be the right naming.
- Fixed hang at POST 5A with certain optical drive.

BIOS Version 0407

About This Release:

- February 18, 2008
- DPP3510J.86A.0407.2008.0218.0923
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.6.0.1011

*Other names and brands may be claimed as the property of others.

- SATA AHCI info:
Version UPSD src 12-03-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Fixed issue where S3 wake will fail intermittently on RAID mode.
- Fixed issue of long boot time due to no media in SATA optical drive when set to AHCI/RAID mode.
- Updated MRC to build 2.4.
- Fixed issue where L2 cache size will not be displayed in BIOS setup.
- Fixed a problem where IERR got asserted on certain CPUs.
- Fixed a problem where the system would hang on S3 resume during SMM relocation.
- Fixed issue where graphics cards that don't support 800x600 mode will not display anything on screen during POST.
- Fixed language switching and 'Exit discard changes' could slow down responsive of BIOS setup page.
- Fixed possible hang at POST code 0x5A with certain video cards attached to the system.
- Added support to select the appropriate voltage based on CPU and FSB speed.
- Fixed a problem where system would boot slow with 8GB of memory in the system, and booting to a 64bit OS.

BIOS Version 0372

About This Release:

- January 29, 2008
- DPP3510J.86A.0372.2008.0129.0418
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.6.0.1011
- SATA AHCI info:
Version UPSD src 12-03-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Fixed manufacturing S3 hang issue.
- Fixed Resume from S3 issue.

BIOS Version 0353

About This Release:

- January 26, 2008
- DPP3510J.86A.0353.2008.0126.0305
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.6.0.1011

*Other names and brands may be claimed as the property of others.

- SATA AHCI info:
Version UPSD src 12-03-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Removed Vista x64 boot performance with 4GB RAM fix.
- Removed fix blue screen during Vista UEFI installation.

BIOS Version 0348

About This Release:

- January 23, 2008
- DPP3510J.86A.0348.2008.0123.2016
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.6.0.1011
- SATA AHCI info:
Version UPSD src 12-03-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Added support for new DP35DP SKU (BOXDP35DPC)

BIOS Version 0345

About This Release:

- January 21, 2008
- DPP3510J.86A.0345.2008.0121.1919
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.6.0.1011
- SATA AHCI info:
Version UPSD src 12-03-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Added support for SATA AHCI Hot-Plug from the Intel Matrix Storage Manager driver.
- Fixed Vista* x64 boot performance with 4GB RAM or more.
- Fixed the IIA Boot Order missing issue.
- Fixed blue screen during Vista UEFI installation.
- Added Intel Rapid Recovery Technology feature.
- Added workaround of option ROM which has an invalid PCI Expansion ROM Header.
- Fixed issue where VGA is not found behind a bridge.
- Fixed POST code 5Ah hang with SATA HDDs and PCI Graphics card in Slot 2.

*Other names and brands may be claimed as the property of others.

- Changed the method of getting ME FW capability through MEBx instead of hard coded.
- Updated processor support.

BIOS Version 0326

About This Release:

- December 06, 2007
- DPP3510J.86A.0326.2007.1206.2256
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.6.0.1011
- SATA AHCI info:
Version UPSD src 08-24-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Updated Chassis Type SMBIOS structure.
- Fixed HDD detection after cold reboot in AHCI mode.
- Updated processor support.

BIOS Version 0305

About This Release:

- November 12, 2007
- DPP3510J.86A.0305.2007.1112.1145
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info:
Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Updated processor support.

BIOS Version 0297

About This Release:

- October 23, 2007
- DPP3510J.86A.0297.2007.1022.2244
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info:
Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

*Other names and brands may be claimed as the property of others.

New Fixes/Features:

- Removed fan detection feature.
- Updated processor support.
- Optimized boot time.
- Set SATA type to IDE by default to avoid blue screen when installing operating system.

BIOS Version 0293**About This Release:**

- October 02, 2007
- DPP3510J.86A.0293.2007.1002.1519
- VBIOS info:
Build Number: 1533 PC 14.27 08/28/2007 09:51:53
- SATA RAID info:
Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info:
Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- G33/P35 BIOS specification update to Rev2.2
- Updated Video ROM to build 1533
- Fixed issue where user need to hit power button twice to power up system when first turn on from AC Off
- Added Software Mode manufacturing mode support.

BIOS Version 0287**About This Release:**

- September 20, 2007
- DPP3510J.86A.0287.2007.0920.1254
- VBIOS info:
Build Number: 1508 PC 14.27 06/08/2007 13:40:32
- SATA RAID info:
Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info:
Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info:
Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Updated DVMT memory size options per IIA requirements
- Updated Video ROM to build 1508
- Updated ICH9 codes to BIOS spec 1.1 updates
- Fixed issue where error message shown when user install invalid payloads for iQST via ITK.

BIOS Version 0276**About This Release:**

*Other names and brands may be claimed as the property of others.

- September 03, 2007
- DPP3510J.86A.0276.2007.0903.1413
- VBIOS info: Build Number: 1471 PC 14.27 03/23/2007 16:54:14
- SATA RAID info: Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info: Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info: Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Updated CK505 clock driver for better multiple platform support.
- Fixed issue where IIA or ITK could not set boot order correctly in both normal and advance boot menu mode.
- Fixed issue where IIA or ITK could not read boot drive model strings
- Fixed issue where ITK or IIA could not access Boot Priority List when all the boot devices disabled in the BIOS Setup

BIOS Version 0267

About This Release:

- August 1, 2007
- DPP3510J.86A.0267.2007.0801.2302
- VBIOS info: Build Number: 1471 PC 14.27 03/23/2007 16:54:14
- SATA RAID info: Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info: Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info: Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Updated MRC to v2.3
- Fixed issue where some USB keyboards may hang up or oversensitive.
- Fixed intermittent failure with EFI_VARIABLE.
- Added support for writing new variable through BIO capsule.
- Added ITK Data Var Type 3 to store VAREQ variable

BIOS Version 0262

About This Release:

- July 23, 2007
- DPP3510J.86A.0262.2007.0723.1620
- VBIOS info: Build Number: 1471 PC 14.27 03/23/2007 16:54:14
- SATA RAID info: Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info: Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info: Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1104

New Fixes/Features:

- Fixed issue of ECIR unable to be detected in OS.
- Fixed incorrect display of cache size for multi-core processors.
- Remove floppy menu screen for boards that don't support it.
- Fixed issue where the BIOS was potentially using all processor variable MTRRs.

*Other names and brands may be claimed as the property of others.

- Updated MRC to version 2.2
- Updated processor support.
- Updated ME FW to build 3.0.1.1104
- Fixed intermittent issue with EFI_VARIABLE in Windows environment
- Fix for initializing custom default values to proper size
- Added dynamic serial and parallel port support
- Fixed issue where Quad core CPU not able to run in single processor mode
- Fixed ACPI failures when running Vista* DTM TCG TPM test
- Fixed slow boot time observed at POST 0x34
- Added QST support for new processors

BIOS Version 0249

About This Release:

- June 25, 2007
- DPP3510J.86A.0249.2007.0625.1327
- VBIOS info: Build Number: 1471 PC 14.27 03/23/2007 16:54:14
- SATA RAID info: Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info: Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info: Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1072

New Fixes/Features:

- Changed SVID of ITE* PATA controller chip back to its default value.
- Fixed issue where BIOS recovery failed to function on systems with more than 2GB memory installed.
- Turn on ME_ENABLE bit in CK505 clock before ME initialization in S3 resume
- Improved S3 resume time by enabling SPI pre-fetching
- Fixed issue where language selection and language display are not matched after user pressed F9/loaded default in BIOS setup.
- Fixed problem of Yellow Bang in Device Manager for Vista* for Mass Storage Controller
- Added dynamic detection of onboard devices for the SMBIOS Type 10 info update.

BIOS Version 0246

About This Release:

- June 13, 2007
- DPP3510J.86A.0246.2007.0613.1659
- VBIOS info: Build Number: 1471 PC 14.27 03/23/2007 16:54:14
- SATA RAID info: Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info: Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info: Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1072

New Fixes/Features:

- Fixed OCUR support
- Fixed Microsoft* OEM Activation 2.0 support
- Added support for CK505 SLG845168BT clock part
- Fixed potential firmware corruption issue

*Other names and brands may be claimed as the property of others.

- Improved S3 resume time by 400msec.
- Updated processor support
- Updated clock part programming
- Fixed issue where Language selection and language display mismatch after pressing Ctrl+Alt+Del
- Added MCH thermal sensor minimal reading note in Hardware Monitoring page.

BIOS Version 0216

About This Release:

- May 02, 2007
- DPP3510J.86A.0216.2007.0502.1916
- VBIOS info: Build Number: 1471 PC 14.27 03/23/2007 16:54:14
- SATA RAID info: Intel(R) RAID for SATA - v7.5.0.1017
- SATA AHCI info: Version UPSD src 04-20-2007 for ICH9
- PXE Nahum info: Intel(R) Boot Agent GE v1.2.50 Beta-1
- ME firmware build: ME FW binary PV build 1072

New Fixes/Features:

- Initial production BIOS release