



BIOS Update Release Notes

PRODUCTS: NUC6i7KYK

BIOS Version - KYSKLi70.86A.0034.2016.0503.1334

About This Release:

- Date: May 3, 2016
- ME Firmware: 11.0.10.1002
- Framework BIOS Reference Code: Based on 1.9.0.0
- Integrated Graphics
 - Option ROM: Build 1037 PC 14.34
 - UEFI Driver: 9.0.1045
- LAN
 - Option ROM: v0104.PXE 2.1 Build 092
- Visual Bios: 2.2.20

New Fixes/Features:

- Updated CPU Microcode.
- Modified Windows Capsule Update platform GUID.
- Fixed watch dog timer issue on first power on.
- Added a fan curve for CPU cool mode.
- Added post-processing for "Max Performance Enable" Setup item.
- When the "Max Performance Enable" power mode is turned on, the FAN controller mode will automatically switch to cool mode.
- Removed the "Fanless" option.
- Modified RST PCIe Storage Remapping Setup behavior.
- When one of the "RST PCIe Storage Remapping" buttons is checked, it will automatically turn off "legacy boot" and enable "UEFI boot".
- Changed voltage adjustment bars:
 - Limited GT slice/unsliced OC ratio range to 28.
 - Limited the maximum Core voltage override/Core extra Turbo and Ring voltage Override/Extra Turbo to 1.5v.
 - Limited the maximum slice Domain/Extra Turbo and Unslice domain/Extra Turbo to 1.5v.
- Fixed Visual BIOS not show the information about the SAMSUNG V950 SSD.
- Modified memory data system slot, and onboard device for SMBIOS.
- Fixed an issue where the system didn't show the model of the SSD and SD Card in the F7 boot menu.
- Fixed an issue where some cooling options didn't show in Integrator Toolkit.
- Fixed an issue where the option "IGD Primary Video Port" and "IGD Secondary Video Port" are incorrect.
- Fixed an issue where "Thunderbolt" was still shown under "IGD Primary Video Port" and "IGD Secondary Video Port" when the Thunderbolt controller was disabled.

*Other names and brands may be claimed as the property of others.

- Fixed an issue where the SD card could read, but not write after resuming from S3.

BIOS Version - KYSKLi70.86A.0033.2016.0408.1727

About This Release:

- Date: April 8, 2016
- ME Firmware: 11.0.10.1002
- Framework BIOS Reference Code: Based on 1.9.0.0
- Integrated Graphics
 - Option ROM: Build 1037 PC 14.34
 - UEFI Driver: 9.0.1045
- LAN
 - Option ROM: v0104.PXE 2.1 Build 092
- Visual Bios: 2.2.20

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, lifesaving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2015 Intel Corporation.