


# Release Notes

## Intel® Wireless Bluetooth® 20.40.0



Package Version and Supported Operating Systems	20.40.0 for Microsoft Windows 10*
---	-----------------------------------

### Supported Products and Driver Versions

Intel® Wireless Adapter	Windows® 10
Intel® Wireless-AC 9560 <sup>1</sup>	20.40.0.3 <sup>1</sup>
Intel® Wireless-AC 9462 <sup>1</sup>	
Intel® Wireless-AC 9461 <sup>1</sup>	
Intel® Wireless-AC 9260 <sup>1</sup>	
Intel® Dual Band Wireless-AC 8265	
Intel® Dual Band Wireless-AC 8260	20.40.0.3
Intel® Dual Band Wireless-AC 3168	
Intel® Dual Band Wireless-AC 3165	
Intel® Wireless 7265 Family	
Intel® Dual Band Wireless-AC 3160	19.41.0.1
Intel® Wireless 7260 Family	

<sup>1</sup>64 Bit only

### Key Issues Fixed and Changes

Description of Key Issue	OS
In some cases Bluetooth fails to reconnect after resuming from airplane mode with Bluetooth mouse and wireless access point connected.	Windows 10®
The Bluetooth device can disappear from the Windows Device Manager after turning Bluetooth off/on repeatedly.	Windows 10®
Bluetooth Low Energy mouse stability improvement during Wake on Bluetooth.	Windows 10®
General stability improvements and optimizations.	All

Note: Key issues fixed in the OS indicated in the table above.



## **Legal Notices**

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at [intel.com](http://intel.com).

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting [www.intel.com/design/literature.htm](http://www.intel.com/design/literature.htm).

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

© February 2018 Intel Corporation.

