



Release Notes

Intel® PROSet/Wireless Software 21.10.1

Supported Operating Systems

- Microsoft Windows 10®
- Microsoft Windows* 8.1
- Microsoft Windows* 7

Supported Products and Driver Versions

Intel® Wireless Adapter	Windows 10®	Windows* 8.1	Windows* 7
Intel® Wi-Fi 6 AX200	21.10.1.2 ¹	n/a	n/a
Intel® Wireless-AC 9560			
Intel® Wireless-AC 9461/ 9462			
Intel® Wireless-AC 9260			
Intel® Dual Band Wireless-AC 8265	20.70.9.1 ¹	19.10.17.2 ¹	19.10.17.2
Intel® Dual Band Wireless-AC 8260			
Intel® Dual Band Wireless-AC 3168	19.51.21.1	19.10.17.2	
Intel® Dual Band Wireless-AC 3165			
Intel® Wireless 7265 Family (Rev.D)	18.33.17.1	18.33.17.1	18.33.17.1
Intel® Wireless 7265 Family (Rev.C)			
Intel® Dual Band Wireless-AC 3160			
Intel® Wireless 7260 Family			

¹64 Bit only

Key Issues Fixed and Changes: Package Version 21.10.1

Description of Key Issue	OS
Windows* stop errors (BSOD) occur during file transfer over Wi-Fi.	Win10
Access points on Channel 165 are slow to appear in the Wi-Fi network scan list.	Win10
After Airplane mode enable/disable cycle, Wi-Fi remains disabled.	Win10
Windows* stop errors (BSOD) may occur during wireless drivers installation.	Win10
Added support for Windows 10 May 2019 Update (19H1).	All

Note: Key issues fixed in the OS indicated in the table above.



Key Issues Fixed and Changes: Package Version 21.0.0

Description of Key Issue	OS
Limited connectivity notification on taskbar when resume from Sleep mode.	Win10
Windows* stop errors (BSOD) may occur during Restart or Sleep/Hibernate cycle.	Win10
WiFi affects Bluetooth throughput performance.	Win10
Windows* stop errors (BSOD) may occur during Internet browsing.	Win10
After system Restart, yellow bang (!) may appear in Device Manager under Intel® Wireless Adapter.	Win7/Win8.1

Note: Key issues fixed in the OS indicated in the table above.



Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

©May 2019 Intel Corporation.

