



Intel® SNMP Subagent v8.1

Release Notes

Release Date: Jan 2020

Build # 14



Legal Statements

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS FOR THE PURPOSE OF SUPPORTING INTEL DEVELOPED SERVER BOARDS AND SYSTEMS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

UNLESS OTHERWISE AGREED IN WRITING BY INTEL, THE INTEL PRODUCTS ARE NOT DESIGNED NOR INTENDED FOR ANY APPLICATION IN WHICH THE FAILURE OF THE INTEL PRODUCT COULD CREATE A SITUATION WHERE PERSONAL INJURY OR DEATH MAY OCCUR.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel is a trademark of Intel Corporation in the U.S. and other countries.

* Other names and brands may be claimed as the property of others.

Copyright © 2007–2020 Intel Corporation. All rights reserved.



1. Package Content

- Intel SNMP Subagent v8.1.1914

2. Supported Operating Systems

- RHEL6*update5 (32 bit & EM64T)
- RHEL7 (EM64T)
- RHEL7.1 (EM64T)
- RHEL7.2 (EM64T)
- RHEL7.3 (EM64T)
- RHEL7.4 (EM64T)
- RHEL7.5 (EM64T)
- RHEL7.6 (EM64T)
- SLES* 11 SP4 (32 bit & EM64T)
- SLES* 12 SP1 (EM64T)

3. Supported Server Platforms

Intel® Server Board based on Intel® Xeon® processor E5-2600 v5 product family”

- Intel® Server Board S2600BP
- Intel® Server Board S2600WF
- Intel® Server Board S2600ST

4. Supported Languages

- Supported languages for Intel® SNMP Subagent
 - English

5. Features

Through basic SNMP GETs and TRAPs, the Intel® SNMP Subagent provides the following functionality for managing servers:

- Accessing sensor data
- Viewing threshold settings
- Reading the SMBIOS tables
- Providing overall system health status



6. Installation & Uninstallation

6.1.1. Installation using standalone installer

- To install SNMP Subagent in Linux, run `snmpsubagentinstall.sh`.

6.1.2. Upgrade

No upgrade available. Uninstall the previous Utilities before installing.

6.1.3. Uninstallation

- Use control panel Add / Remove programs to un-install the Intel® Server Management SNMP Subagent.
- In Linux, run `snmpsubagent_uninstall.sh` or run `uninstall.sh` in the path `/usr/local/snmpsa/bin`

7. Known Issues

- Intel® SNMP subagent is not completely supported in GPT style partitioned OS. The `smbios` and `bios` queries will fail.
- The SNMPSA installer may show these message during installation: "insserv: Script `jexec` is broken: incomplete LSB comment" and "insserv: missing 'Required-Stop:' entry: please add even if empty" due to there is no 'Required-Stop:' in java's `jexec` script. User may need to install latest `java` rpm or add 'Required-Stop:' right below the 'Required-Start:' in `/etc/init.d/jexec` script.
- Intel® SNMP Subagent may not work properly if Intel® IASB is installed on the same system.
- The Intel® SNMP subagent requires that the IPMI driver be started.
To start the IPMI service
Enter "`modprobe ipmi_devintf`" and "`modprobe ipmi_si`" in a linux terminal
*These commands works only if the `openIPMI` package has been installed in the OS.
- `Net-snmp` may record all the successful connections in log file and cause the disk space to be consumed quickly on some Linux OS.
To turn off this logging on SuSE*
 - Change `SNMPD_LOG_SUCCESSFUL_CONNECTIONS="yes"` to "no" in "`/etc/sysconfig/net-snmp`" file
 - Restart `snmpd` and `snmpsa` services.
- Cooling unit sensors, Discrete cooling device table sensors, Drive slot, Power supply, current probe sensors are not available.
- Traps are tested for only Power and Fan. And intermittent traps generation is observed in which case trap messages are not seen continuously.

8. Trouble shooting Instructions

If the Intel® SNMP Subagent or Master locks up, you must restart both agents. Use the following steps from the command line to restart the agents, depending on your operating system. For information on setting services or daemons to start at system boot, see your operating system documentation.



Linux* Operating System

- Stop the subagent by entering the following command:
/etc/init.d/snmpsa stop or systemctl stop snmpsa (for RHEL7 & Above)
- Restart the master agent by entering the following command:
/etc/init.d/snmpd* restart or systemctl restart snmpd (for RHEL7 & Above)
- Start the subagent by entering the following command:
/etc/init.d/snmpsa start or systemctl start snmpsa (for RHEL7 & Above)

*If snmpd file is missing in the path /etc/init.d for Linux OS (esp if RHEL 7 and above) please use "systemctl restart snmpd" or "service snmpd restart" commands in linux terminal.

9. Release change logs

9.1. Build 14

- MIB Browser SNMPSA version issue Fixed
- Release Note Document updated

9.2. Build 13

- Copyright year update in document
- SLES Installation issue Fixed

9.3. Build 12

- Memory Leak Issue is Fixed
- Improper NULL Termination issues is Fixed

9.4. Build 11

- SNMPSA Power supply status mismatch with BMC is fixed.
- SNMPSA Fan Discrete status mismatch with BMC is fixed.
- SNMPSA Fan status mismatch with BMC is fixed.
- SNMPSA Fan Redundancy status mismatch with BMC is fixed.
- SNMPSA Power Unit status mismatch with BMC is fixed.

9.5. Build 10



- Integrated Cacheriver 7.1 build 14.

9.6. Build 9

- Integrated Cacheriver 7.1 build 13.
- Added RHEL 7.3 stable version OS support in the snmpsa install script snmpsubagentinstall.sh.

9.7. Build 8

- SNMP Temperature Threshold for lnr, unr trap OID mismatch for Front temp Sensor is fixed.
- SNMP Temperature Threshold for lnc, unc, ucr trap OID mismatch for Front temp Sensor is fixed.
- SNMP Voltage Threshold for lcr, lnc, unc, ucr trap OID mismatch for Voltage Sensor is fixed.
- SNMP Fan Threshold for lcr, lnc trap OID mismatch for Fan Sensor is fixed.

9.8. Build 7

- Integrated Cacheriver 7.1 build 12.
- Temperature threshold trap OID mismatch for the Front Temp sensor is fixed.
- Fan threshold trap OID mismatch for fan is fixed.

9.9. Build 6

- Integrated Cacheriver 7.1 build 9.
- Added RHEL 7.3 OS support in the snmpsa install script snmpsubagentinstall.sh

9.10. Build 5

- EPSD100254517: [BKC WFP - SLES 12.1 takes more time to shutdown/reboot when SNMPSA utility is installed] is fixed.
- EPSD100254633: [Purley][Sawtooth Pass] [SNMP-SA Build 4 - Fan trap are not generated as expected] is fixed.
- Integrated Cacheriver 7.1 build 8.
- Updated the snmpsubagentinstall.sh to copy the uninstallation script [uninstall.sh] into the path /usr/local/snmpsa/bin.

9.11. Build 4

- Integrated Cacheriver 7.1 build 7.
- Integrated Klocwork code fixes.

9.12. Build 3

- Fixed SNMPSA code for SNMP service hung issue

9.13. Build 2

- Added RHEL 7.2 OS support.



9.14. Build 1

- Integrated Cacheriver 7.1 build2.