

CONTROL CENTER RELEASE NOTES

Version 2.2.0.20

1. Security enhancements.
-

Version 2.2.0.18

1. Changed the **Fan Duty Cycle** behavior so when CCI is first launched CCI will follow the values in the Setup.ini file. After the first launch of CCI, the next time CCI is launched, the BIOS will be able to override the **Fan Duty Cycle**.
 2. Removed mp3 file.
-

Version 2.2.0.16

1. Modified a small part of the Vietnam string (vi-VN) to match Intel requirement.
 2. Removed OEM Service link and "inpoutx64.sys" file.
-

Version 2.2.0.15

1. Modified a small part of incorrect/incomplete string.
-

Version 2.2.0.13

1. Increased the width of the toggle button.
-

Version 2.2.0.12

1. Added the detection method: When CCI is running on the Intel® Whitebook, install Project Aurora. Also, in the following scenarios; When switching keyboard effects or selecting one of the major options on CCI, the CCI UI-AuroraSwitch will be detected.
2. FnKey Lock feature updated.