


October 2020



Release Notes

Intel® PROSet/Wireless Software 22.0.0

Supported Operating Systems

Microsoft Windows 10®

Important Notice: Starting with Software Release 21.50.1, there will be no new driver versions for Windows*7 and Windows* 8.1 Operating Systems.

Supported Products and Driver Versions

<i>Intel® Wireless Adapter</i>	<i>Windows 10®</i>
Intel® Wi-Fi 6E AX210 (Gig+)	22.0.0.6 ¹
Intel® Wi-Fi 6 AX201	
Intel® Wi-Fi 6 AX200	
Intel® Wireless-AC 9560	
Intel® Wireless-AC 9461/ 9462	
Intel® Wireless-AC 9260	
Intel® Dual Band Wireless-AC 8265	20.70.19.1 ¹
Intel® Dual Band Wireless-AC 8260	
Intel® Dual Band Wireless-AC 3168	19.51.31.1
Intel® Dual Band Wireless-AC 3165	
Intel® Wireless 7265 Family (Rev.D)	

¹64 Bit only

Note: This Software Release version does not include new drivers for the Intel® Wireless 7265 Family (Rev.C), Intel® Dual Band Wireless-AC 3160 and Intel® Wireless 7260 Family adapters. Please refer to the following link for latest available drivers [here](#).

Key Issues Fixed and Changes: Package Version 22.0.0

<i>Description of Key Issue</i>	<i>OS</i>
When connected to a Wi-Fi 6 network with 802.11r Fast Roaming is enable, random disconnections occur in enterprise environments.	Win10



Description of Key Issue	OS
Windows* Stop Errors (BSOD) may occur which are associated the Intel Wireless driver.	Win10
When connecting a Wi-Fi 6 adapter to a Wi-Fi 6 Hotspot, the hotspot network information shows connection type as 802.11AC (Wi-Fi 5).	Win10
Intel® PROSet/Wireless Software 22.0.0 has been updated to include functional and security updates. Users should update to the latest version.	Win10

Note: Key issues fixed in the OS indicated in the table above.

Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

©October 2020 Intel Corporation.

