



BIOS Update Release Notes

PRODUCTS: BC510, BC710

BIOS Version 0064 - BCTGL357.0064.2021.0518.1820

About This Release:

- Date: May 18, 2021
- ROM Image Checksum: 0xA869DCCB
- ME Firmware: Consumer 15.0.10.1447 (ROM burner)
- ME Firmware: Consumer 15.0.10.1377 (Capsule update from BC0051/54/57/61)
- EC Firmware: 0.32.00
- PMC Firmware: 150.01.20.1028
- Boot Guard ACM: 1.14.15
- Reference Code: Based on 0A.00.3C.21
- Integrated Graphics:
 - UEFI Driver: 17.0.1045
- Visual BIOS: Intel AptioV
- Supported Flash Devices:
 - WinBond W25Q256FV 32MB
 - GigaDevice GD25B256D 32MB
- Microcode Updates included in .BIN & .CAP Files:
 - M80806C0_00000068.pdb
 - M80806C1_00000078.pdb
 - M80806D0_0000004C.pdb

New Fixes/Features:

- Fix issue when pressing "fn + num-lock" did not switch to the enabled state.
- Fix issue with LCD brightness which dimmed during warm boot process.

BIOS Version 0060 - BCTGL357.0060.2021.0324.1856

About This Release:

- Date: Mar 24, 2021
- ROM Image Checksum: 0xA95F51B1
- ME Firmware: Consumer 15.0.10.1447
- EC Firmware: 0.31.00
- PMC Firmware: 150.01.20.1028
- Boot Guard ACM: 1.14.15
- Reference Code: Based on 0A.00.3C.21
- Integrated Graphics:
 - Option ROM: N/A
 - UEFI Driver: 17.0.1045
- Intel RST Pre-OS:
 - Option ROM: N/A
 - RAID Option ROM: N/A
- Supported Flash Devices:
 - WinBond W25Q256FV 32MB

*Other names and brands may be claimed as the property of others.

- o GigaDevice GD25B256D 32MB
- Microcode Updates included in .BIN & .CAP Files:
 - o M80806C0_00000068.pdb
 - o M80806C1_00000068.pdb
 - o M80806D0_0000004C.pdb

New Fixes/Features:

- Replaced power button menu with security jumper menu in configuration mode.
- Added WLAN disabling feature in Setup, boot to OS, BT is also disabled.
- Updated Retimer Firmware version.
- Added new LAN PXE boot support feature in USB/LAN dongle AX88179 and RTL8152/RTL8153.
- Fixed keyboard FN lock reset after reboot.
- Fixed issues with OFBD module SMI handler.
- Fixed issue with NTFS DXE driver in process of parsing NTFS file system partition.

BIOS Version 0057 - BCTGL357.0057.2021.0203.1856

About This Release:

- Date: Feb 3, 2021
 - o ROM Image Checksum: 0xAEF54B6A
- ME Firmware: Consumer 15.0.2.1377
- EC Firmware: 0.31.00
- PMC Firmware: 150.01.20.1024
- Boot Guard ACM: 1.14.8
- Reference Code: Based on 0A.00.2A.30
- Integrated Graphics:
 - o Option ROM: N/A
 - o UEFI Driver: 17.0.1044
- Visual BIOS: Intel Aptio V
- Supported Flash Devices:
 - o WinBond W25Q256FV 32MB
 - o GigaDevice GD25B256D 32MB
- Microcode Updates included in .BIN & .CAP Files:
 - o M80806C0_00000068.pdb
 - o M80806C1_00000060.pdb
 - o M80806D0_00000030.pdb

New Fixes/Features:

- Updated: EC FW version to 0.31.00.000.
- Fixed: Where you could not boot into BIOS recovery when using a LG 5K Monitor.
- Fixed: Using F7 to update will update the BIOS will also update the ME firmware.
- Fixed: Virtual Number pad that was non-functional.
- Added: Deep S4/S5 option to Setup menu.
- Fixed: iGFX SSID.
- Added: New battery information shown in ESA BIOS setup.

BIOS Version 0051 - BCTGL357.0051.2020.1207.1547

About This Release:

- Date: Dec 8, 2020
- ROM Image Checksum: 0xACB7574B
- ME Firmware: Consumer 15.0.2.1377
- EC Firmware: 0.28.00
- PMC Firmware: 150.01.20.1024
- Boot Guard ACM: 1.14.8
- Reference Code: Based on 0A.00.2A.30
- Integrated Graphics:
 - Option ROM: N/A
 - UEFI Driver: 17.0.1044
- Visual BIOS: Intel AptioV
- Supported Flash Devices:
 - WinBond W25Q256FV 32MB
 - GigaDevice GD25B256D 32MB
- Microcode Updates included in .BIN & .CAP Files:
 - M80806C0_00000068.pdb
 - M80806C1_00000060.pdb
 - M80806D0_00000030.pdb

New Fixes/Features:

- Fixed Issue: Touch panel ghost point during LID open / LID close
- Functionality Updates

BIOS Version 0048 - BCTGL357.0048.2020.1118.2111

About This Release:

- Date: Nov 18, 2020
- ROM Image Checksum: 0xAE1E7966
- ME Firmware: Consumer 15.0.2.1377
- EC Firmware: 0.28.00
- PMC Firmware: 150.01.20.1024
- Boot Guard ACM: 1.14.8
- Reference Code: Based on 0A.00.2A.30
- Integrated Graphics:
 - Option ROM: N/A
 - UEFI Driver: 17.0.1044
- Intel RST Pre-OS:
 - Option ROM: N/A
 - RAID Option ROM: N/A
- Supported Flash Devices:
 - WinBond W25Q256FV 32MB
 - GigaDevice GD25B256D 32MB
- Microcode Updates included in .BIN & .CAP Files:
 - M80806C0_00000068.pdb
 - M80806C1_00000060.pdb
 - M80806D0_00000030.pdb

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

*Other names and brands may be claimed as the property of others.

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2021 Intel Corporation.

*Other names and brands may be claimed as the property of others.