

# Intel® Extreme Tuning Utility v10.0.1.45

Version Number: 10.0.1.45

Release Type: Production Release

Release Date: 27/03/2026

Release details and installation details are as follows:

## Changes

- Updated ISO (Intel® Speed Optimizer) table for ARL Refresh processors:
  - Intel® Core™ Ultra 200S Plus
  - Intel® Core™ Ultra 200HX Plus
- Bump telemetry artifact from 3.1.175.0 to 3.1.185.0.
- Bump libiomp5md artifact from 2021.2.0\_109 to 2025.0.0\_771

## Driver(s) included in release

Name	Version
Watchdog Device Driver	11.7.0.1021

- Driver(s) required for this release

Name	Minimum Version	Download Link
Intel® Innovation Platform Framework	2.2.10200.11	<a href="https://www.intel.com/content/www/us/en/download/826464/intel-innovation-platform-framework.html">https://www.intel.com/content/www/us/en/download/826464/intel-innovation-platform-framework.html</a>

## Known Behavior (s)

- The IGCL Provider is required for Graphics Frequency monitoring.
- Graphics Voltage monitoring is unavailable.
- System Agent Voltage monitor is unavailable.

## Fixed Issue(s)

- None

## Chipset Requirements

- Intel® Extreme Tuning Utility for unlocked Intel® Core™ Ultra processors requires a chipset that supports full overclocking (IA, BCLK, Memory). For full, up-to-date details about OC support for processors and chipsets, visit <https://ark.intel.com/content/www/us/en/ark.html>

#### **Supported Platforms:**

- ArrowLake -S
- ArrowLake- HX

#### **Supported Operating Systems:**

- Windows 10 22H2
- Windows 11 22H2
- Windows 11 23H2
- Windows 11 24H2
- Windows 11 25H2

*Note: XTU is supported on 64-bit Operating systems only.*